

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 30054
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	B-9613
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	94
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>L</u> : <u>2550</u> Feet From The <u>SOUTH</u> Line and <u>130</u> Feet From The <u>WEST</u> Line Section <u>32</u> Township <u>24S</u> Range <u>38E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-02-98: MIRU. POH W/RDS & FND 7/8" CPLG PARTED. TIH W/FSHNG TOOL.
3-03-98: UNFLANGE WH & NUBOP. TAG DN W/TBG & TAG W/2'. SCANALOG TBG OUT OF HLE.
3-04-98: TIH W/SWEDGE, BS, & JARS. TAG @ 6423'. SWEDGE 1 1/2" IN 1 HR. TITE SPOT @ 6424-27, 6454-60, 6467-72'.
3-05-98: TIH W/SWEDGE & WRK 6467-72 & WRK OUT. TIH W& TAG DN @ 6514'. TIH W/4 1/4" SWEDGE -WRK THRU TITE SPOTS. TIH W/4 5/8" SWEDGE & WRK 6424-27'.
3-06-98: TIH W/4 1/2" BIT & BAILER.
3-09-98: BAIL 6514-6525'. TIH W/2 7/8" NOTCHED COLLAR & BAILER. TAG @ 6514' & WRKD BAILER THRU TO 6530'. TIH TO 6667 & TAG SOLID.
3-10-98: TIH W/SONIC HAMMER TOOL & HOOK UP TO ACIDIZE. TBG PLGD. TIH W/SONIC HAMMER TOOL & ACIDIZE PERFS W/3000 GALS 15% HCL.
3-11-98: TIH W/MUD JT, SN, TAC & 2 7/8" TBG. SET TAC & NDBOP. FLANGE UP WH.
3-12-98: TIH W/PMP & RDS & TAG DN @ 1400' W/PMP. NUBOP. PULL TBG & FND NEW JT TBG W/CRIMP. LD JT & REPLACE. TIH W/TBG & NDBOP.
3-13-98: TIH W/PMP & RDS. HANG ON & LOAD & TEST. RD.
3-22-98: ON 24 HR OPT. PUMPED 18 BO, 58 BW, & 34 MCFD.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 3/23/98

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY TITLE REP. # DATE

CONDITIONS OF APPROVAL, IF ANY: REP. #