

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
310 Old Santa Fe Trail, Room 206
Santa Fe, New Mexico 87503

WELL API NO. 30-025-30151
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. Agreement 8910084910
7. Lease Name or Unit Agreement Name West Dollarhide Queen Unit
8. Well No. 95
9. Pool name or Wildcat Dollarhide Queen
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator SAGA PETROLEUM LLC	
3. Address of Operator 415 W WALL, SUITE 1900 MIDLAND, TX 79701	
4. Well Location Unit Letter <u>L</u> : <u>2630</u> Feet From The <u>South</u> Line and <u>910</u> Feet From The <u>West</u> Line Section <u>32</u> Township <u>24S</u> Range <u>38E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐
CASING TEST AND CEMENT JOB ☐
OTHER: SQZ ADD PERFS ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-1-2000 RIH w/retainer, break circ w/73 bbls 2% KCL, set retainer 3680', test tbg to 2000, good. No show of communication above retainer.

7-5 Mix & pump 75 sx Class C w/1% CaCl, displace w/19 BW. Sting out of retainer pump 1/4 bbl dwn tbg to start cmt moving, reverse out, rec approx 1 to 1-1/2 bbl cmt. Pump additional 10 bbls to clean up. POOH w/tbg

7-6 Perf @ 3600-3662' w/2 JSPF, 24 holes. Swab to frac tank 4 hrs, rec 145 BW, IFL surf, FFL 2400'.

7-8 RIH w/114 jts 2-7/8" 6.4# Tbg to 3657', SN @ 3620' TAC 3273.50'. 63- 1575' 3/4" sucker rods, 68- 1700' 7/8" sucker rods & 1- 25-200-RHBC-16-4 pump

7-11 Well produced 4 BO & 330 BW
8-13 Well produced 6 BO & 248 BW

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE PRODUCTION ASSISTANT DATE 08/15/2000

TYPE OR PRINT NAME BONNIE HUSBAND

TELEPHONE NO. (915)684-4293

(This space for State Use)

ORIGINAL SIGNED BY CLARA WILLIAMS
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

