STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

		
MO. BF COPIES RECEIVED		
MOITUBIRTEID		
BANTA PE		
FILE		
U.S.G.S.	<u> </u>	
LAND OFFICE		
OPERATOR		

UIL CONSERVATION DIVISION P. O. BOX 2088

Form	C - '	103	
Revis	ьs	10-	1-79

SANTA FE		1	SANTA FE, NEW	MEXICO 87501	1		V641250 13-	1-13
FILE						5d, Indicate Ty	pe of Lease	
U.S.G.S.		1				State XX	Fea	
LAND OFFI	- E					5. State Off & C	Gas Lease No.	=_
OPERATOR		ل				B-9519		
						ririn	mmm	11.
(DO NOT U	LE YHIS FORM FOR PRO	DPGSALS TO PAIL	AND REPORTS ON	SACK TO A DIFFERENT RE	SERVOIR.			7/
one Cas other- Water injection well					7. Unit Agreement Name West Dollarhide Oueen Sand Unit			
2. Name of Operato			acer injection			8. Farm of Lea		
0-11	ian Tma							
Sirgo-Coll:						9. Well No.		
P. O. Box 3531, Midland, Texas 79702						112		
4. Location of Well	3531, Midiano	i, lexas	19102			10. Field and Pool, or Wildcat		
		51Q	South	568		·		
UNIT LETTER _	M	DIO FEE	T FROM THE South	LINE AND	FEET FROM	7777777	mimm	77,
Wee	+	29	TOWNSHIP 24S	38E	2			
THE WES	LINE, SECTIO	ON	TOWNSHIP	RANGE	NMPM.			///
mmm	mmm	177777 15.	Elevation (Show whether	DF, RT, GR, etc.)		12. County	17:11:11:11	14
		. / / / / / /	70' GR			Lea		
16.	777777777	777777			D 0.1	D :		**
		• •	Box To Indicate N	vature of Notice,	-		_	
	NOTICE OF II	VIENTION 1	го:		SUBSEQUENT	REPORT OF	·:	
PERFORM REMEDIAL	- WORK		PLUG AND ABANDON		님		ERING CASING	VV
TEMPORARILY ABAN	DON	2		COMMENCE DRILLING	7	PLUG	AND ABANDONMENT	MA
PULL OR ALTER CAS	ING		CHANGE PLANS	CASING TEST AND CEN	APL THEN			
				OTHER				
OTHER					•			
17. Describe Propo work) SEE RU		perations (Clear	rly state all pertinent det	ails, and give pertinen	t dates, including	estimated date o	f starting any prop	osed
		_ 1 -				allorro Do	wistions	
The West D	ollarhide Qu	een Sand (Jnit #112 was pl	Lugged and abar	ndoned as I	DITOMS. DE	eviations effica in	
	pproved prop	osed procu	ıdures were appı	oved by Jerry	Sexton of	the MMOCD C	TITCE III	
Hobbs.								
	- 05	0.07001	0 100 0 10	2001 1000	d soment A	15221		
2-18-88	Set 35 sx	@ 2/20.	Set 100 sx @ 19	ou and tagged	d Cement @	1923 •		
			eline retreivabl	la packar a 150	001 Sauge	zed 50 sv (15231	
2-22-88			eline retreivab.	te packet @ 150	oo . squee.	2ed J0 5x (1525 •	
	Pulled the	packer.			4.			
	a . 50	5 1200	-1026'. Set 75	av from ///0-1	21! Sat 1	n ev a euri	ace.	
2-23-88				SX IIOM 440 I.	21 • 500 1	O DA C BULL	acci	
	Cut off ca	sing and	set P&A marker.					
				•				
	÷		•					
						•		
				af == 1=================================	aliaf			
18. I hereby certify	that the information	n above is true	and complete to the best	of my knowledge and p	enel.			

OIL & GAS INSPECTOR

Agent

March 7, 1988

1988 OFFICE