Energy nerals and Natural Resources Department

Form C-103

Revised 1-1-80

District All 2	Revised 1-1-69
OIL CONSERVATION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	30 025 30229
P.O. Box Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease
DISTRICT III	STATE ☑ FEE ☐
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil / Gas Lease No. B-9613
SUNDRY NOTICES AND REPORTS ON WELL	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)	WEST DOLLARHIDE DRINKARD UNIT
1. Type of Well: OIL S GAS OTHER	
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.	8. Well No. 93
Address of Operator 205 E. Bender, HOBBS, NM 88240	9. Pool Name or Wildcat DOLLARHIDE DRINKARD
4. Well Location	
	Feet From The <u>EAST</u> Line
Section 32 Township 24S Range 38E NM	
10. Elevation (Show whether DF, RKB, RT,GR, etc.) GR 3185 k	KB 3200
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPE	RATION PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEMEN	IT JOB 🔲
OTHER: OTHER:	HORIZONTAL LATERAL
1-24-98: MIRU. UNSEAT PUMP & LD SNKR BARS. 1-27-98: TIH W/2 7/8" TBG & PKR TO 5115. TEST BOP & CSG. 1-28-99: TIH W/78G & DC'S. DRILL ON CIBP @ 6445'. CRACKED PLUG & LOST CIRC. 1-29-99: DRILG ON PLUG @ 6445. PSh DN TO 6497'. PU CSG SCRAPER TO 6497'. 1-30-98: LD TBG. RUN GAUGE RING TO 6492'. SET CIBP @ 6482'. PSA 6474'. 2-07-98: MOVE DIRECTIONAL TRAILER TO LOCATION & TIE INTO POWER LINE. 2-10-98: NUBOP. TIH W/DP. TAG @ 6474'. SET WHIPSTOCK. CUT WINDOW. 2-11/17 98: DRILLING. TIH W/HIPSTOCK RET TOOL. TIH W/BMPR SUB, JARS, DC'S & DP. SCREW ONTO FSH. TIH W/MILL SHOE. 2-19-98: MILL ON WHIPSTOCK. TIH & WORK ONTO FSH. MIRU WL. SET TBG & rBP @ 6364'. MILL ON WINDOW & O.H. @ 6360'. 2-20/24 98: DRILLING. TIH W/RBP ON DP @ 5500'. TIH W/45 JTS TBG'. 3-05-98: RDBOP. TIH W/RETR TOOL ON WS. LATCH ONTO RBP. 3-06-98: UNLOAD & RACK 2 7/8" TBG & 3 1/2" FRAC TBG. TIH W/PLUG, TBG, JET SUB & PKR. 3-07-98: TIH W/FRAC TBG TO END OF LATERAL @ 7462'. PSA 6100'. NU FRAC TREE. 3-10-98: CIRC W/70 BBLS 10# BRINE. TIH W/HOOK, BMPR SUB ON TBG TO 6354'. LATCH INTO WHIPSTOCK. TIH W/2 7/8" TBG. 3-12-98: CIRC W/70 BBLS 10# BRINE. TIH W/HOOK, BMPR SUB ON TBG TO 6354'. LATCH INTO WHIPSTOCK. TIH W/2 7/8" TBG. 3-13-98: REL RBP. LD WS. LEFT RBP @ TBG @ 2500' FOR KILL STRING. 3-14-98: CIRC ANNULAS W/60 BBLS 10# BRINE. RAN PLUG, JET SUB, TBG. TAG BTM (JUNK) @ 6402'. PULL TBG TO 6200'. 3-17-98: TOH W/FRAC TBG & PKR. TIH W/MILL. 3-18-98: LOWER MILL & TOOLS. PSH FSH TO 6399'. 3-19-98: TOH W/FRAC TBG & FOOLS. RUN TBG INTO LATERAL @ 7133'. PULL 30 JTS TO 6300'. 3-21-98: WKK BENT SUB INTO LOWER LATERAL 6398-7256' W/40,000 GALS 15% NEFE ACID.	
3-24-98: REL PKR. LD PKR & TBG. RAN 2 7/8" TBG TO 3110'. 3-26-98: RAN MOTOR, PUMP, 2 7/8" TBG. REM BOP. INSTL TBG HEAD. SUB PUMP @ 6294'. ON PROD @ 6:45 PM. RIG DOWN 3-27-98. 4-10-98: INSTL BOP. PULL SUB PUMP.	
I hereby certify that the information above fitture and complete to the olds of my knowledge and belief.	
SIGNATURE SIGNATURE Engineering Assistant	DATE
TYPE OR PRINT NAME J. Denise Leake	Telephone No. 397-0405
ORIGINAL SIGNED BY CHRIS WILLIAMS DISTRICT I SUPERVISOR	DATE NOV 0 . OW
APPROVED BYTITLETITLETOUR STATES TO SHOW THE STATES TO SHOW THE SHOW	UAIL ***** · · · · · · · · · · · · · · · ·
	5.5