

Submit 3 Copies
to Appropriate
District Office
District I
P.O. Box 1980, Hobbs, NM 88240
District II
P.O. Box 1980, Hobbs, NM 88240
District III
P.O. Box 1980, Hobbs, NM 88240

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONVERSATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 - 025 - 30287 ✓
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B9613
7. Lease Name or Unit agreement Name	WEST DOLLARHIDE QN SD UT
8. Well No.	110
9. Pool name or Wildcat	DOLLARHIDE QUEEN

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTION	
2. Name of Operator OXY USA INC.	
3. Address of Operator P.O. Box 50250 Midland, TX 79710	
4. Well Location Unit Letter C : 820 Feet From The NORTH Line and 1,570 Feet From The WEST Line Section 32 Township 24 S Range 38 E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Complete Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any work) SEE RULE 1103.

TD - 3900' PBTD - 3875' PERFS - 3656' - 3830'

MIRU PU, NDWH, NUBOP, POOH W/ PKR & 2-3/8" TBG. RIH & TAG @ 3870', CLEAN OUT TO 3875'. PERFORATE ADD'L INTERVAL 3715-17, 3741-44, 3787-3791, 3806-07, 3811, 3828-3830', TOTAL 38 HOLES. ACIDIZED W/ 1000 GAL 15% NEFE HCL ACID. RIH W/ BAKER AD-1 & 2-3/8" TBG, SET PKR @ 3587', NDBOP, NUWH. PRESS CSG TO 350#, HELD OK, RDP. START INJECTING 332 BWPD @ 1290#.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 04 16 93
TYPE OR PRINT NAME David Stewart TELEPHONE NO. 915 685-5717

(This space for State Use)
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

APR 1 9 1993

C. J. B.

