

UNIT STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
NEW MEXICO 88210

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM 15317

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Paduca Unit

8. FARM OR LEASE NAME

Paduca Unit

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Unit I, Sec. 23-25S-32E

12. COUNTY OR PARISH 13. STATE

Lea

NM

1. (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

105 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FSL & 660' FEL, Sec. 23-T25S-R32E

14. PERMIT NO.

API #30-025-30387

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3426.6' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Perforate, Treat

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

6-8-89. TOOH w/RBP and packer. TIH and set RBP 13106', set packer 12804'. Tested packer and RBP to 4000 psi, OK.

6-9-89. WIH on wireline with 1-11/16" tubing gun and perforated 12949-13029' w/11 .30" holes as follows: 12949, 51, 52, 61, 69, 83, 92, 94, 13009, 27 and 13029'.

6-10-89. Acidized perfs 12949-13029' w/2500 gals 15% NEFE acid and ball sealers.

6-11 - 6-23-89. Swabbed and tested well.

7-19-89. RUPU. WIH and retrieved RBP, moved plug to 12723'. Tested to 3000 psi. TOH w/packer.

7-22-89. WIH with 4" casing gun and perforated 9242-68' w/27 .42" holes (1 SPF). Picked up 7-5/8" RBP and packer. TIH to 9200'. Set RBP 9370'. POOH to 9120'.

Acidized perfs 9242-68' w/3000 gals 7 1/2% acid and ball sealers.

7-23 - 24-89. Swabbed and tested.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature]

TITLE Production Supervisor

DATE 7-25-89

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

AUG 08 1989

*See Instructions on Reverse Side

SSS
CARLSBAD, NEW MEXICO

RECEIVED

AUG 11 1989

OCD
HOBBS OFFICE