Submit 3 Copies to Appropriate District Office

## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

Revised 1-1-4

District Office		
DISTRICT I P.O. Box 1980, Hobbs, NM 88240  DISTRICT II P.O. Drawer DD, Artesia, NM 88210  DISTRICT III 1000 Rio Brazos Rd., Azzec, NM 87410  OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088		WELL API NO.
		30-025-30822  5. Indicate Type of Lease
		STATE X FEE
CUMPRY MOTICES AND REPORTS ON WELLS		B-9613
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name WEST DOLLARHIDE DRINKARD UNIT
I. Type of Well: OR. OAS WELL X WELL OTHER		
2. Name of Operator TEXACO PRODUCING INC.		8. Well No. 100
3. Address of Operator		9. Pool name or Wildcat
P. O. Box 3109 Midland, Texas 79702		DOLLARHIDE TUBB DRINKARD
Unit Letter M : 1169 Feet From The SOUTH Line and 120 Feet From The WEST Line		
Section 29 Township 24-SOUTH Range 38-EAST NMPM LEA County  10. Elevation (Show whether DF, RKB, RT, GR, etc.)		
//////////////////////////////////////	, , , , , , , , , , , , , , , , , , , ,	
11. Check Appropriate Box to Indicate		•
NOTICE OF INTENTION TO:	SUE	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLIN	G OPNS. DPLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND C	EMENT JOB .
OTHER:	OTHER: COMPLETE	ON X
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a work) SEE RULE 1103.	nd give pertinent dates, incli	iding estimated date of starting any proposed
1. MIRU CLARKE WELL SERVICE. CLEAN OUT TO PBTD OF 6 2. UNION RAN GR-CCL. PERF w/ 1 JSPF: 6681-89, 6691-9 6772-76, 6778-81, 6786-90, 6808-14, 6817-20, 6824- GAL 15% NEFE. SWAB 12 HOURS 11-26-90. RECOVERED 5 3. TIH & SET RBP @ 6650'. TEST TO 3000#. PERF w/ 1 JS 6516-19, 6527-36, 6543-48, 6550-59, 6562-81. 83 HOI SWAB 10 HOURS 12-1-90. RECOVERED 6 BNO & 81 BLW. 7 4. RAN 2 7/8 TUBING, PUMP & RODS. 5. PUMPED 24 HOURS 12-6-90. RECOVERED 60 BNO, 23 BI 6. PREP TO POTENTIAL.	94, 6701-07, 6724- 34, 6836-40. 64 HO BNO & 43 BLW. SPF: 6448-51, 6455 LES. HALLIBURTON A FOH WITH RBP.	-26, 6729-32, 6746-50, 6754-58, DLES. HALLIBURTON ACIDIZED w/ 6300 5-62, 6473-77, 6480-6500, 6506-10,
Spirition Landing and the spiriting and the spir	d belief. ITLE DRILLING SUPERI	INTENDENT DATE 12–11–90 TELEPHONE NO. 915–68846
TYPE OR PRINT NAME C. P. BASHAM		IDEATHOR NO. 0.10 30040
(This space for State Use)		

\_ TITLE -

APPROVED BY ---