

Submit 3 Copies To Appropriate District
Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

WELL API NO. 30-025-30823
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-9613
7. Lease Name or Unit Agreement Name: West Dollarhide Drinkard Unit
8. Well No. 101
9. Pool name or Wildcat Dollarhide Tubb Drinkard

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Chevron USA, Inc.

3. Address of Operator
15 Smith Rd. Midland, Tx 79705

4. Well Location
Unit Letter D : 121 feet from the north line and 166 feet from the west line
Section 32 Township 24-S Range 38-E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Prior to R/U tbg stuck w/Tac & Rods-tbg parted @ 6320 +- top of rod @4000 +- ok to sqz w/200sx fr/4000-6375(ok w/Gary Wink)
2. Sqz w/200sx fr/4000-6375 Tag @ 4010(Test sqz ok)
3. Displace hole w/MLF 9.5# Brine w/25 # Gel P/BBL
4. Perf 4 holes 3900 sqz w/100sx fr/3900-3700(Queen D.V. Tool) Tag @ 3660
5. Spot 25sx plug fr/2800-2600(yates, B-salt) Tag @ 2558
6. Spot 25sx plug fr/1300-1100 (11 3/4 shoe,T-salt) Tag @ 1073
7. Circ cmt fr/400 to surf w/50sx fr/400 to surf Tag @ surf.
- 8.

Approved as to Plugging of the Well Bore.
Liability under bond is retained until
Surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE MANAGER/SUNSET DATE 11-25-02

Type or print name Jimmy BABLEY Telephone No 915 520-8752

(This space for State use) ORIGINAL SIGNED BY CHRIS WILLIAMS **DEC 13 2002**

APPROVED BY OC DISTRICT SUPERVISOR/GENERAL MANAGER TITLE DATE

Conditions of approval, if any: