

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 South First, Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103

Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-30823
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator Texaco Exploration & Production, Inc.		6. State Oil & Gas Lease No. B-9613
3. Address of Operator P. O. Box 3109, Midland, TX 79702		7. Lease Name or Unit Agreement Name: West Dollarhide Drinkard Unit
4. Well Location Unit Letter <u>D</u> : <u>121</u> feet from the <u>North</u> line and <u>166</u> feet from the <u>West</u> line Section <u>32</u> Township <u>24S</u> Range <u>38E</u> NMPM Lea County		8. Well No. 101
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Dollarhide Tubb/Drinkard

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Set 5 1/2" CIBP @ 6375'. Spot 25 Sx plug 6375'-6175' (Tubb-Drinkard) WOC Tag
2. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL
3. Spot 40 Sx plug 4050'-3700' (Queen, DV Tool)
4. Spot 25 Sx plug 2800'-2600' (Yates, B-Salt) WOC Tag
5. Spot 25 Sx plug 1300'-1100' (11 3/4" shoe, T-Salt) WOC Tag
6. 10 Sx Surface, Install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James T. Corbitt TITLE FACILITY ENGINEER DATE 9/24/01
Type or print name JAMES T. CORBITT Telephone No. 915 688-4438
(This space for State use)

APPROVED BY _____ TITLE _____ DATE _____
Conditions of approval, if any:

PLUGGING & ABANDONMENT WORKSHEET (3 STRING CSNG)

OPERATOR Texaco Exploration & Production
LEASENAME WEST DOWNSHIDE Drinkard UNIT

		WELL #	101
SECT	<u>32</u> TWN	<u>24S</u> RNG	<u>38 E</u>
FROM	<u>121</u> NSL	<u>166</u> EWL	
TD:	<u>6880</u>	FORMATION @ TD	Drinkae
PBTD:	<u>6860</u>	FORMATION @ PBTD	TUBB

MLF

MLF

MLF

MLF

$11 \frac{3}{4}$
 @ 1200
 TOC 50'

Dr @ 3992

5 1/2
@ 6875
TOC SURF

TD 6880

	SIZE	SET @	TOC	TOC DETERMINED BY	
SURFACE	11 3/4	1200	50'	TS	
INTMED 1					
INTMED 2					
PROD	5 1/2	6875	SUEF	CIRC	
	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1					
LINER 2					
	CUT & PULL @			TOP - BOTTOM	
INTMED 1			PERFS	6432 - 6823	
INTMED 2			OPENHOLE	-	
PROD					

*** REQUIRED PLUGS DISTRICT I**

RUSTLER (ANHYD)	
YATES	
QUEEN	
GRAYBURG	
SAN ANDRES	
CAPTAN REEF	
DELAWARE	
BELL CANYON	
CHERRY CANYON	
BRUSHY CANYON	
BONE SPRING	
GLORIETA	
BLINEBRY	
TUBB	
DRINKARD	
ABO	
WC	
PENN	
STRAWN	
ATOEA	
MORROW	
MISS	
DEVONIAN	

[illegible]