

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30823
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-9613
7. Lease Name or Unit Agreement Name WEST DOLLARHIDE DRINKARD UNIT
8. Well No. 101
9. Pool name or Wildcat DOLLARHIDE TUBB DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator TEXACO PRODUCING INC.	
3. Address of Operator P. O. Box 3109 Midland, Texas 79702	
4. Well Location Unit Letter <u>D</u> : <u>121</u> Feet From The <u>NORTH</u> Line and <u>166</u> Feet From The <u>WEST</u> Line Section <u>32</u> Township <u>24-SOUTH</u> Range <u>38-EAST</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3165', KB-3179'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: COMPLETING <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU CLARKE WELL SERVICE. CLEAN OUT TO PBTD OF 6860'. TESTED CASING TO 3000# FOR 30 MINUTES 12-9-90.
2. UNION RAN GR-CCL. PERFED w/ 1 JSPF: 6604-07, 6614-16, 6638-40, 6649-54, 6712-16, 6731-34, 6739-43, 6820-23. 26 HOLES. HALLIBURTON ACIDIZED WITH 4300 GAL 15% NEFE. 12-11-90. SWAB 10 HOURS. RECOVERED 5 BNO, 5 BFW, & 183 BLW.
3. TIH & SET RBP @ 6595'. TEST TO 3000#. PERF w/ 1 JSPF: 6432-35, 6439-44, 6448-55, 6457-61, 6477-81, 6511-13, 6518-23, 6541-43, 6549-53, 6582-86. 40 HOLES. HALLIBURTON ACIDIZED w/ 5000 GAL 15% NEFE. 12-14-90. SWAB 9 HOURS 12-15-90. RECOVERED 21 BNO, 39 BFW & 92 BLW.
4. TOH WITH RBP. TIH WITH 2 7/8 TUBING, PUMP & RODS.
5. PUMPED 24 HOURS 12-26-90. RECOVERED 40 BNO, 250 BFW & 39 MCF.
6. TESTING.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C.P. Basham / cwt TITLE DRILLING SUPERINTENDENT DATE 12-27-90
TYPE OR PRINT NAME C. P. BASHAM TELEPHONE NO. 915-6884620

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: