

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30825
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-9613
7. Lease Name or Unit Agreement Name WEST DOLLARHIDE DRINKARD UNIT
8. Well No. 103
9. Pool name or Wildcat DOLLARHIDE TUBB DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator TEXACO PRODUCING INC.	
3. Address of Operator P. O. Box 3109 Midland, Texas 79702	
4. Well Location Unit Letter <u>J</u> : <u>2577</u> Feet From The <u>SOUTH</u> Line and <u>2510</u> Feet From The <u>EAST</u> Line Section <u>32</u> Township <u>24-SOUTH</u> Range <u>38-EAST</u> NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3199', KB-3217'	

11.

(Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: COMPLETING ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU CLARKE UNIT. CLEAN OUT TO PBTD OF 6850'. TESTED CASING TO 3000# FOR 30 MINUTES (8-8:30pm)02-03-91.
2. UNION RAN GR-CCL. PERFED w/ 1 JSPF: 6660-62, 6693-99, 6705-08, 6718-21, 6724-27, 6733-35, 6769-72, 6774-76, 6790-95, 6798-6803, 6808-6813. 39 HOLES. HALLIBURTON ACIDIZED w/ 5200 GAL 15% NEFE. 02-05-91. SWAB 29 BNO & 114 BLW IN 6 HOURS.
3. TIH WITH RBP. SET @ 6650' & TEST TO 2800#. BURST CASING. BACKED OFF 5 1/2 CASING @ 18'. CASING HAD 18 inch SPLIT @ 12'. TIH WITH NEW JT OF 5 1/2 CASING. MADE UP IN COLLAR. TESTED CASING TO 1000#. HALLIBURTON DUMPED 10 SACKS OF CLASS H DOWN SURFACE CASING. TESTED CASING TO 3000# 2-9-91.
4. UNION PERFED w/ 1 JSPF: 6483-85, 6489-95, 6501-13, 6519-23, 6533-40, 6548-53, 6599-6604, 6619-21, 6631-34. 46 HOLES. BROKE PERFS w/ 200 GAL 15% NEFE 02-09-91.
5. WELL FLOWED 50 BNO & 10 BLW IN 6 HOURS 02-11-91. TOH WITH RBP.
6. TIH WITH 2 7/8 TUBING, PUMP & RODS. SEATING NIPPLE @ 6825'.
7. WELL PUMPED 24 HOURS 02-24-91. RECOVERED 131 BNO, 183 BW & 64 MCF.
8. TESTING.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C.P. Basham/cwh TITLE DRILLING SUPERINTENDENT DATE 02-25-91

TYPE OR PRINT NAME C. P. BASHAM

TELEPHONE NO. 915-6884620

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

FEB 28 1991

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: