

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 30826
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-9613
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	104
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD

SUJNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>J</u> : <u>2541</u> Feet From The <u>SOUTH</u> Line and <u>1380</u> Feet From The <u>EAST</u> Line Section <u>32</u> Township <u>24S</u> Range <u>38E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK: ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ ACIDIZE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-05-00: MIRU. UNSEAT PUMP. NDWH. NUBOP., REL TAC.
1-06-00: TIH W/BIT, CSG SCRAPER, 2 7/8" TBG TO 6646'. TIH W/KILL STRING TO 1600'.
1-07-00: TIH W/LOG TOOL. RUN GR/CCL 6632-6100'. TIH W/PERF GUN. PERF CSG IN DRINKARD FORMATION 6484-88,6491-6509, 6512-20, 6528-33, 6546-53,6561-64. TIH W/PKR, SN, & TBG. TEST TO 5000 PSI. PSA 6388'. LOAD & PSI CSG TO 500 OK.
1-10-00: PRESS CSG TO 500#-OK. ACIDIZE DRINKARD CSG PERFS 6484-6634' W/6000 GALS 15% NEFE HCL & 3000# RK SLT. RU SWAB. FL @ 700'. END FL @ 4800'.
1-11-00: BLED WELL DN. FL @ 4500'. END FL @ 4600'. RD SWAB. RU PUMP TRUCK & SCALE SQUEEZE DRINKARD PERFS 6484-6634 W/110 GALS TH-756 + 2 GALS ALPHA-133 MIXED IN 20 BBLs 2% KCL WTR. FLSH W/75 BBLs 2% KCL WTR + 3 GALS ALPHA 133.
1-12-00: REL PKR & TIH TO 6646'. TIH W/OPSMA W/SAND SCREEN, SN, TBG, TAC. NDBOP. NUWH. MA @ 6620. SN @ 6587'. TAC @ 6422'. TIH W/GAS ANCHOR, SNKR BARS & RDS.
1-13-00: HANG ON LOAD & TEST TO 500#-OK. CHECK PUMP ACTION-OK. RIG DOWN. PUMPING @ 12:30 PM.
2-09-00: ON 24 HR OPT. PUMPED 26 BO, 95 BW, & 38 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 2/14/00
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL: F ANY TITLE DATE