

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 30830
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-9613
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	108
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	3177' GL

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>M</u> : <u>1201</u> Feet From The <u>SOUTH</u> Line and <u>156</u> Feet From The <u>WEST</u> Line Section <u>33</u> Township <u>24S</u> Range <u>38E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	3177' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ ACIDIZE

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-07-99: MIRU. NDWH. NUBOP. REL TAC.
6-08-99: TIH W/BIT & CSG SCRAPER & TBG TO 6599'.
6-09-99: TIH W/SONIC HAMMER ON TBG. ACID WASH DRINKARD PERFS 6479-6562' W/2000 GALS 15% NEFE HCL. RU SWAB. FL @ 1400'. END FL @ 3800'.
6-10-99: TIH W/PKR, SN & 2 7/8" TBG. PSA 6436'. RU PUMP TRUCK. LOAD & TEST CSG TO 500# W/65 BBLS 2% KCL WTR.
6-11-99: PRESS CSG TO 300#-OK. ACIDIZE DRINKARD PERFS 6479-6562' W/4000 GALS 15% NEFE HCL & 2500# RK SLT. RU SWAB. FL @ SURF. END FL @ 3800'. RD SWAB. SCALE SQUEEZE W/10 GALS TH-430 + 1 GAL ALPHA 133.
6-12-99: REL PKR. TIH W/OPSM, SN, TBG, TAC. NDBOP. SET TAC. NUWH. MA @ 6535'. SN @ 6506'. TAC @ 6310'. TIH W/GAS ANCHOR, PUMP & RDS. HANG ON. LOAD & TEST. SPACE OUT. RIG DOWN. PUMPING
7-10-99: ON 24 HR OPT. PUMPED 12 BO, 58 BW, & 4 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 7/22/99

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use) **ORIGINAL SIGNED BY** WINK

APPROVED BY CP. II TITLE CP. II DATE JUL 27 1999

CONDITIONS OF APPROVAL, IF ANY: