

RECEIVED

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Dec 23 10 43 AM '92

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Texaco Exploration and Production Inc.

3. Address and Telephone No.

P.O. Box 730, Hobbs, NM 88240

505-397-0428

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit Letter K, 2008' FSL, 2022' FWL

Section 35, T-24-S, R-37-E

FORM APPROVED

Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

LC - 032874- A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

G.L. Erwin A Fed. #5

9. API Well No.

30 - 025 - 30875

10. Field and Pool, or Exploratory Area

North Justis Drinkard

11. County or Parish, State

Lea

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☒ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other Recomplete to Blinebry
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- (1) MIRU, pull rods and pump. NU BOP. Pull tubing.
- (2) Clean casing to 6600' with scraper and gauge ring. POH. Set CIBP at 5600'.
- (3) Rig up wireline. Perforate Blinebry from 5305'-5325' w/ 4 spf.
- (4) GIH with 3-1/2" tubing and 5-1/2" packer. Set at 5250'.
- (5) Fracture treat Blinebry with 50,000 gallons 30# cross-linked gel, 165,649# 16/30 Ottawa sand and 50,000# resin coated sand.
- (6) GIH with work string and reverse unit and clean out wellbore. POH. Rerun production string, ND BOP and run rods and pump. Put well on test.

14. I hereby certify that the foregoing is true and correct

Signed

R. McNaughton

Title Production Engineer

Date 12-13-92

(This space for Federal or State office use)

Approved by

David R. Glass

Title

Date 1/12/93


Conditions of approval, if any:

Lea County, New Mexico

TABULAR DATA

Hole Size 7-7/8, DV tool set at 5782'

Tubing: 2 7/8", 4.7#, J-55, SN at 6136'



Abo 6253'