

W2
Submit 3 Copies
to Appropriate
District Office

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Benzon Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-163
Revised 1-1-89

WELL API NO. 30-025-31482
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-9613
7. Lease Name or Unit Agreement Name WEST DOLLARHIDE DRINKARD UNIT
8. Well No. 113
9. Pool name or Wildcat DOLLARHIDE TUBB DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3140', KB-3158'

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. Name of Operator TEXACO EXPLORATION AND PRODUCTION INC.	
3. Address of Operator P. O. Box 3109 Midland, Texas 79702	
4. Well Location Unit Letter M : 136 Feet From The SOUTH Line and 1246 Feet From The WEST Line Section 32 Township 24-SOUTH Range 38-EAST NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3140', KB-3158'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	CASING TEST AND CEMENT JOB ☐
	PLUG AND ABANDONMENT ☐
	OTHER: COMPLETION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU COMPLETION UNIT. TIH & TAG PBTD @ 7385'. TESTED CASING TO 3000# FOR 30 MINUTES. 10-7-92.
2. UNION RAN GR-CCL FROM 7385' TO 6200'. PERF w/ 1 JSPF: 7166-72, 7178-86, 7194-97, 7209-16. 26 HOLES. DOWELL ACIDIZED w/ 2700 GAL 15% NEFE 10-9-92. SWAB 8 BO & 124 BLW IN 6 HOURS.
3. TIH & SET RBP @ 7095' & TESTED TO 3000#. PERFED w/ 1 JSPF: 6788-98, 6818-22, 6841-45, 6860-66, 6894-98, 6950-55, 6958-60, 6972-80, 6992-96, 7034-38. 59 HOLES. DOWELL ACIDIZED w/ 5300 GAL 15% NEFE. 10-13-92. SWB 64 BO & 90 BLW IN 4 HOURS.
4. MOVED RBP TO 6730' & TESTED TO 3000#. PERFED w/ 2 JSPF: 6308-12, 6331-34, 6338-51, 6356-66, 6370-72, 6378-6400, 6506-09, 6538-42, 6549-55, 6558-71, 6610-15, 6622-28, 6644-47, 6654-58. 196 HOLES. DOWELL ACIDIZED w/ 10300 GAL 15% NEFE 10-16-92. FLOWED 8 BO & 196 BLW IN 6 HOURS.
5. TOH WITH RBP.
6. TIH WITH 2 7/8 TUBING, PUMP AND RODS.
7. PUMPED 43 BO AND 313 BLW IN 15 1/2 HOURS 10-20-92.
8. TESTING.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. P. Basham / cwb TITLE DRILLING OPERATIONS MANAGER DATE 10-21-92
TELEPHONE NO. 915-6884620

TYPE OR PRINT NAME C. P. BASHAM

(This space for State Use)

APPROVED BY Paul Kautz TITLE Geologist DATE NOV 05 '92
CONDITIONS OF APPROVAL, IF ANY: