

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-025-31489

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-9613

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
WEST DOLLARHIDE DRINKARD UNIT

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER WATER INJECTION

2. Name of Operator
TEXACO EXPLORATION AND PRODUCTION INC.

8. Well No.
122

3. Address of Operator
P. O. Box 3109 Midland, Texas 79702

9. Pool name or Wildcat
DOLLARHIDE TUBB DRINKARD

4. Well Location
Unit Letter K : 2055 Feet From The SOUTH Line and 1981 Feet From The WEST Line

Section 32 Township 24-SOUTH Range 38-EAST NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
GR-3168', KB-3186'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: COMPLETION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU SERVICE UNIT. CLEAN OUT CEMENT TO PBTD OF 7600'. TESTED CASING TO 3000# FOR 30 MINUTES 01-08-93.
2. UNION RAN GR-CCL. PERFERED w/ 2 JSPF: 7006, 7014-22, 7028, 7034-40, 7050, 7076, 7083, 7088, 7094, 7112, 7126-30, 7142-58, 7198-7208, 7292-7308, 7329-37, 7350-54, 7407-21. 188 HOLES.
3. DOWELL ACIDIZED PERFS 7292-7421 WITH 4150 GAL 15% NEFE. 01-09-93.
4. DOWELL ACIDIZED PERFS 7006-7208 WITH 4200 GAL 15% NEFE. 01-10-93.
5. UNION SET CIBP @ 6975' AND CAPPED WITH 20' OF CEMENT. NEW PBTD IS 6955'.
6. PERFERED w/ 2 JSPF: 6446-54, 6494-6502, 6516-22, 6526-31, 6534-41, 6558-62, 6566-68, 6590-94. 88 HOLES.
7. DOWELL ACIDIZED WITH 5200 GAL 15% NEFE. 01-16-93. SWAB 101 BO, 47 BLW IN 5 HOURS.
8. TIH WITH 2 3/8 TUBING AND PACKER. SET PACKER @ 6389'.
9. TESTED PACKER TO 400# FOR 30 MINUTES 01-24-93.
10. PREP FOR INJECTION.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. P. Basham / cwt TITLE DRILLING OPERATIONS MANAGER DATE 01-25-93

TYPE OR PRINT NAME C. P. BASHAM

TELEPHONE NO. 915-6884620

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JAN 27 1993