State of New Mexico Energy, erals and Natural Resources Department	Form C-103
Submit 3 Copies	Revised 1-1-89
to Appropriate District Office OIL CONSERVATION DIVISION	WELL API NO.
DISTRICT I P.O Box 2088	30-025-31736
P.O. Box 1980, Hobbs, NM 88240 Santa Fe, New Mexico 87504-2008	5. Indicate Type of Lease
P.O. Drawer DD, Artesia, NM 88210	STATE FEE X
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS)	7. Lease Name or Unit Agreement Name  Ida Wimberley
1. Type of Well: OIL GAS GAS	
WELL X WELL other  2. Name of Operator	8. Well No.
ARCO OIL and GAS COMPANY	19
3. Adress of Operator	9. Pool Name or Wildcat
P.O. Box 1610, Midland, Texas 79702	Justis Tubb Drinkard
4. Well Locaztion	
Unit Letter E 2250 Feet From The North Line and 3	30 Feet from The West Line
Section 25 Township 25S Range 37E NMI	PM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc. 3061 GR	.)
Check Appropriate Box To Indicate Nature of Notice, Rep	port, or Other Data
	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI	
PULL OR ALTER CASING CASING TEST AND CEMEN	AL JOB 🔽
(Other) (Other)	
12. Describe Proposed or completed Operation(Clearly state allpertinent dates, including estimated date of star	ling any proposed
Work) SEE RULE 1103.  Core #1 5016'-5106, #2 5106'-5196', #3 5196'-5286', #4 5286'-5376', #5 5376'-546' #8 5643'-5733', #9 5733'-5823', #10 5823'-5913'.  TD'd 7-7/8" hole at 6080', 11-5-92. Ran logs. Ran 5-1/2 15.5# csg to 6080 w/DV tool at w/6% gel + 3% salt followed by 200 sx "H" w/8 pps CSE + .6% CF-14 + .35% T-lite. second stage w/725 sx PSLC w/6% gel + 3% salt followed by 100 sx "C". Circ 65 sx to	3275. Cmt'd first stage w/315 sx PSLC Open DVT & circ out 118 sx to surf. Cmt
11-11-92. RUPU. DO DVT. Press test 5-1/2 csg to 1000# for 30 min. Tag PBD at 6029 Swab test 3-1/2 days.	. Perf Tubb f/5881-5884. A w/1000 gals.
11-16-92. Perf Blinebry f/5303-5358. Set RBP at 5698. A w/2000 gals. Swab test 3 day tbg to 5962. Rods & pump. RDPU 11-20-92.	ys. POH w/RBP at 5698. RIH w/CA. 2-7/8
11-25-92. In 24 hrs pmpd 45 BO, 66 BW, 29 MCF.	
18 hereby certify that the information above is true and complete to the best of my knowledge and belie	
SIGNATURE Regulatory Coo	rdinator 12-1-92
TYPE OR PRINT NAME Ken W. Gosnell	тецернов (915) 688-5672
(This space for State Use)  ORIGINAL SIGNED BY JERRY SEXTON  ORIGINAL SIGNED BY JERRY SEXTON	DEC 07 '9
BISTRICT I SUPERVISOR	DATE

CONDITIONS FOR APPROVAL, IF ANY: