Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 **Revised 1-1-89**

District Office OIL CONSERVATION DIVISION DISTRICT I WELL API NO. P.O. Box 1980, Hobbs NM 88240 P.O. Box 2088 30-025-31867 DISTRICT II Santa Fe, New Mexico 87504-2088 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 STATE L FER X DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) South Justis Unit "F" 1. Type of Well:
OIL
WELL GAS WELL OTHER Water Injection 2. Name of Operator 8. Well No. **ARCO Permian** 192 3. Address of Operator 9. Pool name or Wildcat P.O. Box 1710, Hobbs, New Mexico 88240 Justis Bly Tubb Drkd 4. Well Location Line and 1560 Feet From The Unit Letter Feet From The Section 24 Township 25S Range 37E County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3078' GR 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data **NOTICE OF INTENTION TO:** SUBSEQUENT REPORT OF: PERPORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND CEMENT JOB OTHER: Set CIBP & Add Perfs OTHER: 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. TD: 6150' CIBP: 5510' INJECTION INTERVAL: 4994-5482' 03/28/97: POH w/2-3/8" IPC tbg & pkr. WIH w/bit, scraper, & 2-3/8" workstring to 5600'. WIH and set 4-1/2" CIBP @ 5510'. WIH w/3-1/8" guns & perf 4994-5062, 44 holes, 2 JSPF.

63/29/97: Set pkrs @ 5185 & 5201'. Pmp 2050 gals 15% NEFE HCL w/20 bbls 2% KCL. Acidized old & new perfs from 4994-5196'. POH w/workstring. 03/30/97: WIH w/4-1/2" Guiberson G VI pkr & 2-3/8" IPC tbg, set @ 4925.13'. Press up csg to 500%, held for 30 mins. Chart attached. 43/28/97: POH w/2-3/8" IPC tbg & pkr. WIH w/bit, straper; & 2-3/8" workstring to 3600". WIH and set 4-1/2" CIDP 5510". WIH w/3-1/8" gams & perf 4994-5062, 44 holes; 2 JSPF.
43/29/97: Set place 5185 & 5201'. Pmp 2050 gals 15% NBFB HCL w/20 bbls 2% KCL. Acidized old & new perfs from 4994-5196'. P^field Administrative Assistant THE MINE admin asst SIGNATURE Z TYPE OR PRINT NAME MUTTISE (This space for State OR) GINAL SIGNAD BY JERRY SEXTON &PR 11 1997 DISTRICT I SUTERVISOR APPROVED BY

TILE



CONDITIONS OF APPROVAL, IF ANY:

DATE

