

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 31971
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	123
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter M : 1275 Feet From The SOUTH Line and 200 Feet From The WEST Line
Section 32 Township 24-S Range 38-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3137', KB-3150'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐ HORIZONTAL LATERAL ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-12-98: MIRU. PULL RDS. NUBOP. TOH W/TBG.
5-13-98: BLEED OFF 100 PSI TBG PRESS. PU WINDOW & MILLS ON 2 7/8" TBG & TIH TO 6325'. TOH & LD TBG. TIH W/GUAGE RING TO 6325'. TIH W/PKR & SET @ 6299'.
5-21-98: TIH W/LATCH ASSEMBLY, SUB, & DP TO 6260'. STING INTO PKR @ 6299'. SET WHIPSTOCK @ 6249'. MILL FR 6240-6241'.
5-22-98: MILL & DRILL FORM TO 6250'. TIH W/TBG. RUN GYRO. DRILLING THROUGH 5-30-98. SET RBP @ 6000'.
5-31-98: LDDP. RIG RELEASED @ 9:00 AM
6-01-98: MIRU. REC & TALLY 3 1/2" TBG. PRESS TEST BOP/CSG TO 100 PSI-OK. TIH W/RBP & TBG TO 5896'.
6-02-98: TIH TO 6000 W/RBP. REL RBP & TOH. TIH & ENTER LATERAL #1L. SET PKR @ 6219'. NU 10000 PSI 3 1/2" FRAC TREE.
6-04-98: PRESS TEST LINES @ 10000 PSI-OK. ACID FRAC EAST DRINKARD LATERAL DN 3 1/2" TBG W/60,000 GALS 15% NEFE HCL & 70,000 GALS WF130. FLOW BACK TBG TO TANK.
6-05-98: ND FRAC TREE & OPEN PACKER BYPASS. PUMP 10 BW DN CSG & TBG. TOH W/ TBG & PKR. TIH W/RBP & SET @ 6220'. TIH W/BAILER & DUMP 5' SD ON RBP. TIH W/960' KILL STRING.
6-06-98: TIH & ENTER UPPER LATERAL. PSA 8496'. NU 10,000 PSI FRAC TREE & TEST CSG/PKR TO 500 PSI-OK. RIG DOWN.
6-09-98: PRESS TEST LINES TO 10,000 PSI-OK. ACID FRAC WEST DRINKARD LATERAL DN 3 1/2" TBG W/60,000 GALS 15% NEFE HCL & 70,000 GALS WF130. FLOW BACK FRAC ON 14/64" CHOKE.
6-10-98: ND FRAC TREE. REL PKR. TOH W/FRAC STRING. TIH TO 5865'.
6-11-98: TAG 5' SD ON RBP/TBG TO 100 PSI-CSG-0 PSI. TIH W/3 1/2" TBG. TOH W/TBG & LD.
6-12-98: SET RBP @ 2012'. TEST CSG TO 500 PSI-OK. NDBOP. NU MANUAL BOP STACK & TEST TO 500 PSI-OK. REL RBP.
6-13-98: TOH W/3500' 2 7/8" TBG. TIH W/SUB PUMP, MOTOR, GAS SEPERATOR. RAN 187 JTS 2 7/8". NDBOP. NUWH & TIE INTO ELECTRICAL CABLE & WH. RIG DOWN SERVICE UNIT.
6-16-98: ON 24 HR OPT. PUMPED 327 BO, 576 BW, & 216 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 7/20/98

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED BY _____ TITLE _____

DATE _____

CONDITIONS OF APPROVAL, IF ANY: