

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31972
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-9613
7. Lease Name or Unit Agreement Name WEST DOLLARHIDE DRINKARD UNIT
8. Well No. 125
9. Pool name or Wildcat DOLLARHIDE TUBB DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator TEXACO EXPLORATION AND PRODUCTION INC.	
3. Address of Operator P. O. Box 3109 Midland, Texas 79702	
4. Well Location Unit Letter N : 1150 Feet From The SOUTH Line and 1400 Feet From The WEST Line Section 33 Township 24-SOUTH Range 38-EAST NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3169', KB-3182'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: COMPLETION <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU SERVICE UNIT CLEANED OUT TO PBTD @ 7500'. TESTED CASING TO 3000# FOR 30 MINUTES 07-03-93.
2. HLS RAN GR-CCL. PERFED WITH 2 JSPF: 6740-6750, 6755-6763, 6793-6815, 6819-6840, 6909-6915, 7027-7030, 7084-7093, 7096-7102, 7106-7108, 7430-7444. 202 HOLES.
3. TIH W/ RBP & PACKER. SET RBP @ 7481'. DOWELL ACIDIZED W/ 3900 GAL 15% HCL ON PERFS 7027'-7444'. 07-07-93.
4. RELEASE PACKER & RETRIEVE RBP. RESET RBP @ 7006'. TEST RBP TO 3000#. SET PACKER @ 6687'.
5. DOWELL ACIDIZED W/ 5201 GAL 15% HCL ON PERFS 6740'-6915' 07-07-93.
6. TIH RELEASE PACKER & RETRIEVE RBP. SET RBP @ 7481'. SET PACKER @ 6679'. SWAB 40 BO IN 10 HRS. 07-09-93.
7. TIH RELEASE PACKER & RBP @ 7480'. SET PACKER @ 6196'. TESTED RBP TO 6200#. SET RBP @ 6893'.
8. PERFED W/ 4 JSPF: 6498-6502, 6506-6521, 6534-6547, 6554-6587. 260 HOLES.
9. RELEASE PACKER @ 6650'. TOH W/ PACKER & TUBING. DOWELL FRAC'D W/ 42000 GAL 35# XLG WATER & 23000# 20/40 SD.
10. RETRIEVE RBP. TIH W/ 2 7/8 TUBING, RODS AND PUMP.
11. PUMPED 275 BO, 190 BW, 157 MCF IN 24 HOURS. 07-24-93.
12. TESTING.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. P. Basham / SDH TITLE DRILLING OPERATIONS MANAGER DATE 07-27-93

TYPE OR PRINT NAME C.P. BASHAM

TELEPHONE NO. 915-6884620

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

III 29 1993

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: