

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-31973

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
B-9613

7. Lease Name or Unit Agreement Name
WEST DOLLARHIDE DRINKARD UNIT

8. Well No.
126

9. Pool name or Wildcat
DOLLARHIDE TUBB DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION AND PRODUCTION INC.

3. Address of Operator
P. O. Box 3109 Midland, Texas 79702

4. Well Location
Unit Letter L : 2450 Feet From The SOUTH Line and 150 Feet From The WEST Line

Section 33 Township 24-SOUTH Range 38-EAST NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
GR-3176', KB-3189'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: COMPLETION ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU SERVICE UNIT TIH TO PBTD @ 7507'. TESTED CASING TO 3000# FOR 30 MINUTES 07-17-93.
2. HLS RAN GR-CCL. PERFED W/ 2 JSPF: 6693-6696, 6721-6727, 6735-6742, 6854-6857, 6890-6896, 6903-6905, 6916-6919, 6927-6930, 6934-6936, 6980-6985, 7002-7006, 7018-7030, 7081-7086, 7091-7098, 7126-7136, 7174-7178, 7192-7196, 7238-7242, 7333-7350, 7410-7416. 226 HOLES.
3. TIH W/ RBP & PACKER. SET RBP @ 7426'. DOWELL ACIDIZED W/ 5001 GAL 15% HCL ON PERFS 6980'-7416' 07-19-93.
4. RELEASE PACKER & RETRIEVE RBP. RESET RBP @ 6971'. TEST RBP TO 3000#. SET PACKER @ 6678'.
5. DOWELL ACIDIZED W/ 3500 GAL 15% HCL ON PERFS 6693'-6936'. 07-19-93.
6. SWAB 15 BO IN 11 HRS. 07-20-93.
7. PERFED W/ 4 JSPF: 6464-6471, 6483-6486, 6491-6494, 6497-6511, 6516-6520, 6528-6537, 6545-6551, 6557-6566, 6572-6580, 6610-6613, 6624-6628. 280 HOLES.
8. ACID/FRAC'D W/ 15000 GAL 65 QUALITY CO2 FOAM 20% HCL AND 7500 GAL 65 QUALITY CO2 FOAM 10 PPG BRINE. RETRIEVE RBP. TIH W/ 2 7/8 TUBING, RODS & PUMP.
9. PUMPED 40 BO, 160 BW, 39 MCF IN 24 HRS. 08-02-93.
10. TESTING.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE C. P. Basham / SDH TITLE DRILLING OPERATIONS MANAGER DATE 08-03-93

TYPE OR PRINT NAME C.P. BASHAM

TELEPHONE NO. 915-6884620

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

AUG 06 1993