

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002532015
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-9613
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	130
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3195', KB-3208'

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	OIL WELL ☐ GAS WELL ☐ OTHER WATER INJECTION
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>G</u> : <u>2000</u> Feet From The <u>NORTH</u> Line and <u>1900</u> Feet From The <u>EAST</u> Line Section <u>32</u> Township <u>24-SO</u> Range <u>38-EA</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3195', KB-3208'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Clean out & Acidize ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-29-99: MIRU. NDWH. NUBOP. REL INJ PKR. TIH W/TBG & TAG FILL @ 6512' 45' BELOW PKR. C/O RAMS ON BOP. LEFT FLOWING TO FRAC TANK.
4-30-99: RU REV UNIT. TIH W/BIT & DC'S. PU WS. TAG FILL @ 6521'. C/O SCALE & IRON SULFIDE TO 6667'. FELL THRU. LOWER TOOLS TO 7049'. CIRC CLN. PULL TO 5800'.
5-01-99: TIH W/PERF GUN & PERF IN DRINKARD FORM 6508-12, 16-29, 34-38. TIH W/SONIC HAMMER TOOL ON WS TO 6490'.
5-03-99: ACID WASH W/SONIC HAMMER PERFS 6508-6658' W/4000 GALS 15% NEFE HCL. WASH PERFS 6548-6655' W/2000 GALS & PERFS 76508-6538' W/2000 GALS. FLOW WELL TO TANK.
5-04-99: TIH W/WRP & SET @ 6545'. TIH W/RET TOOL & PKR, SN ON TBG. MISFIGURED TALLY & TAG TOP OF WRP. LATCH & REL WRP @ 6545'.
5-05-99: TIH W/WRP & RESET @ 6545'. TIH W/RET TOOL, PKR ON TBG. PSA 6457'. LOAD & TEST CSG TO 500#-OK. ACIDIZE DRINKARD PERFS 6508-6538' W/4000 GALS 15% NEFE HCL & 2000# RK SLT. FLOW WELL TO FRAC TANK.
5-06-99: REL PKR & TIH TO WRP @ 6545'. LATCH & REL WRP. TIH W/PJR, ON/OFF TOOL, SN. LEAVE PKR SWINGING @ 6473'.
5-07-99: RU PUMP TRUCK. CIRC W/125 BBLs PKR FLUID. PSA 6473'. NDBOP. NUWH. TEST PKR & CSG TO 500 PSI & CHART FOR NMOC-OK. RIG DOWN.
5-20-99: ON 24 HR OPT. INJ 230 BWPD @ 1500#. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 6/3/99
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use) ORIGINAL SIGNED BY GARY W. WINK TITLE FIELD REPRESENTATIVE II DATE 6-29-99
APPROVED BY GARY W. WINK TITLE FIELD REPRESENTATIVE II DATE 6-29-99
CONDITIONS OF APPROVAL, IF ANY:

