

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	3002532162
5. Indicate Type of Lease	STATE ☐ FEE ☐
6. State Oil / Gas Lease No.	B-9613
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	140
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3195', KB-3208'

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☐ GAS WELL ☐ OTHER WATER INJECTION

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter J : 1980 Feet From The SOUTH Line and 1850 Feet From The EAST Line
Section 32 Township 24-SO Range 38-EA NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) GR-3195', KB-3208'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☒ Acidize

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-10-99: MIRU. NDWH. NUBOP. REL PKT. TIH W/BIT ON 2 7/8" TBG TO 6453'.
5-11-99: TAG FILL @ 6497'. BREAK CIRC W/REV UNIT. C/O IRON SULFIDE & SCALE TO 6610'-FELL THRU. LOWER TOOLS TO 7000'. CIRC CLN. RD REV UNIT. TIH W/CSG GUN. PERF DRINKARD FORM 6457-60, 6464-70, 6473-77, 6480-86'. TIH W/SONIC HAMMER, 2 7/8" SN ON 205 JTS 2 7/8" TBG TO 6425'.
5-12-99: ACID WASH DRINKARD PERFS 6457-6612' W/SONIC HAMMER W/4000 GALS 15% NEFE HCL. WASH PERFS 6457-86' W/2000 GALS 15% . RU SWAB. FL @ SURF. END FL @ 1200'.
5-13-99: TIH W/WRP SET @ 6492'. TIH W/RET TOOL, PKR, & SN ON 2 7/8" TBG. SET PKR @ 6395'. PRESS CSG TO 500#-OK. ACIDIZE DRINKARD PERFS 6457-6486' W/4000 GALS 15% & 2500# RK SLT. FLOW WELL TO FRAC TANK.
5-14-99: REL PKR. TIH & TAG SALT FILL @ 6486'. RU PUMP TRUCK. CIRC 6' SLT OFF WRP @ 6492'. LATCH & REL WRP. C/O RAMS ON BOP. TIH W/PKR, ON/OFF TOOL, PROF NIP. KB-13'. INSTL STRIPPER HEAD.
5-15-99: RU PUMP TRUCK & CIRC HLE W/125 BBLS PKR FLUID. PSA 6432-25' ABOVE TOP PERF. NDBOP. NU INJ HEADER. TEST CSG & PKR & CHART FOR NMOC D FOR 30 MINS-TO 500#-OK. INSTL INJ LINE. RIG DOWN. START INJ.
5-19-99: ON 24 HR INJ. INJ'G 600 BWPD @ 1330#. FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 6/3/99

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use) GARY W. WINK ORIGINAL SIGNED BY GARY WINK

APPROVED BY FIELD REPRESENTATIVE II TITLE FIELD REP. II DATE 6-29-99

CONDITIONS OF APPROVAL, IF ANY:

