	JNITED STA MENT OF TH AU OF LAND M	E INTERIOR	P.O. BOX	1980	COMMISSION Budget Bureau No. 1004-0135	
2011			HOBBS, N	IEW ME	5. Lease Designation and Serial No.	
SUNDRY NO	<b>OTICES AND RE</b>	PORTS ON WE	115			
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.					LC 032582-B 6. If Indian, Allottee or Tribe Name	
	CATION FOR PERMI				of the matter of the matter	
	BMIT ORIGINAL PLU	IS 5 COPIES			7. If Unit or CA, Agreement Designati	
1. Type of Well						
	ther			[	8. Well Name and No.	
2. Name of Operator PRIME OPERATING COMPANY 3. Address and Telephone No. 915 682-5600 731 W. Wadley, Bidg. L-220, Midland, TX 79705					WELLS B-1 #6	
					9. API Well No.	
				•	30-025-32345 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T		escription)			JALMAT (YATES, SR	
				ł	11. County or Parrish, State	
660' FNL & 1980' FEL, Sec. 1, T-255	5, R-36E	Knit B			LEA, N.M.	
12. CHECK APPROP	PIATE POY(c) T					
TYPE OF SUBMISSION		C INDICATE NA		OF ACTIC	REPORT, OR OTHER DATA	
Notice of Intent		Abandonment	ITE		Change of Plans	
_		Recompletion			New Construction	
X Subsequent Report		Plugging Back			Non-Routine Fracturing	
-		Casing Repair			Water Shut-Off	
Final Abandonment N	otice	Altering Casing			Conversion to Injection	
		X Other: Spud & S	Setting of Casing		Dispose Water	
					te: Report results of multiple completion on Well npletion or Recompletion Report and Log form.)	
any proposed work. If well is direction pertinent to this work.) 1. Spudded 12 1/4" hol 2. Drilled to 1206'. 3. On 12-19-93 set <u>9 5//</u> 4. Cemented 9 5/8" cas 5. WOC 18 hours. Test	ally drilled, give subsur le @ 10:00 pm 12-16 §", 36#, ST&C casin sing with 710 sacks ed BOP, casinghead	93. g @ 1206' using 13 Premium Plus w/2%	easured and true centralizers. cacl. Circ 150 sa	vertical dep acks to su	oths for all markers and zones	
any proposed work. If well is direction pertinent to this work.) 1. Spudded 12 1/4" hol 2. Drilled to 1206', 3. On 12-19-93 set <u>9 5//</u> 4. Cemented 9 5/8" car 5. WOC 18 hours. Test 6. Resumed drilling 8 7. Drilled to 3030'. 8. Ran DST #1 from 29 9. Drilled to 3100'. 10. Ran open hole logs 11. On 12-26-93 set 7", 12. Cemented 7" casin	ally drilled, give subsur le @ 10:00 pm 12-16 §", 36#, ST&C casin sing with 710 sacks red BOP, casinghead 3/4" hole. 50'-3030'. 5. ,20#, J-65, ST&C cas g with 220 sacks Pre	rface locations and m 93. 9 @ 1206' using 13 Premium Plus w/2% 1 and casing to 1000 and casing to 1000 mium Plus Light ce	easured and true centralizers. caci. Circ 150 s for 30 minutes for 30 minutes ment, tailed in w	vertical dep acks to su . Held OK vith 150 sa	oths for all markers and zones	
any proposed work. If well is direction pertinent to this work.) 1. Spudded 12 1/4" hol 2. Drilled to 1206'. 3. On 12-19-93 set <u>9 5//</u> 4. Cemented 9 5/8" cas 5. WOC 18 hours. Test 6. Resumed drilling 8 7. Drilled to 3030'. 8. Ran DST #1 from 29 9. Drilled to 3100'. 10. Ran open hole logs 11. On 12-26-93 set 7", 12. Cemented 7" casin	ally drilled, give subsur le @ 10:00 pm 12-16 §", 36#, ST&C casin sing with 710 sacks red BOP, casinghead 3/4" hole. 50'-3030'. 5. ,20#, J-65, ST&C cas g with 220 sacks Pre	rface locations and m 93. 9 @ 1206' using 13 Premium Plus w/2% 1 and casing to 1000 and casing to 1000 mium Plus Light ce	easured and true centralizers. caci. Circ 150 s for 30 minutes for 30 minutes ment, tailed in w	vertical dep acks to su . Held OK vith 150 sa	oths for all markers and zones	
any proposed work. If well is direction pertinent to this work.) 1. Spudded 12 1/4" hol 2. Drilled to 1206', 3. On 12-19-93 set <u>9 5//</u> 4. Cemented 9 5/8" car 5. WOC 18 hours. Test 6. Resumed drilling 8 7. Drilled to 3030'. 8. Ran DST #1 from 29 9. Drilled to 3100'. 10. Ran open hole logs 11. On 12-26-93 set 7", 12. Cemented 7" casin	ally drilled, give subsur le @ 10:00 pm 12-16 §", 36#, ST&C casin sing with 710 sacks red BOP, casinghead 3/4" hole. 50'-3030'. 5. ,20#, J-65, ST&C cas g with 220 sacks Pre	rface locations and m 93. 9 @ 1206' using 13 Premium Plus w/2% 1 and casing to 1000 and casing to 1000 mium Plus Light ce	easured and true centralizers. caci. Circ 150 s for 30 minutes for 30 minutes ment, tailed in w	vertical dep acks to su . Held OK vith 150 sa	oths for all markers and zones	
any proposed work. If well is direction pertinent to this work.) 1. Spudded 12 1/4" hol 2. Drilled to 1206'. 3. On 12-19-93 set 9 5// 4. Cemented 9 5/8" cas 5. WOC 18 hours. Test 6. Resumed drilling 8 7. Drilled to 3030'. 8. Ran DST #1 from 29 9. Drilled to 3100'. 10. Ran open hole logs 11. On 12-26-93 set 7", 12. Cemented 7" casin 13. Ran temp. survey. 14. WOC 18 hours. Test 15. Resumed drilling 6	ally drilled, give subsur le @ 10:00 pm 12-16 8", 36#, ST&C casin sing with 710 sacks ed BOP, casinghead 3/4" hole. 50'-3030'. 5. 20#, J-65, ST&C cas g with 220 sacks Pre Top of cement @ 11 sted BOP, casinghea 1/4" hole.	rface locations and m 93. 9 @ 1206' using 13 Premium Plus w/2% 1 and casing to 1000 and casing to 1000 mium Plus Light ce	easured and true centralizers. caci. Circ 150 s for 30 minutes for 30 minutes ment, tailed in w	vertical dep acks to su . Held OK vith 150 sa	oths for all markers and zones	
any proposed work. If well is direction pertinent to this work.) 1. Spudded 12 1/4" hol 2. Drilled to 1206'. 3. On 12-19-93 set 9 5// 4. Cemented 9 5/8" cas 5. WOC 18 hours. Test 6. Resumed drilling 8 7. Drilled to 3030'. 8. Ran DST #1 from 29 9. Drilled to 3100'. 10. Ran open hole logs 11. On 12-26-93 set 7", 12. Cemented 7" casin 13. Ran temp. survey. 14. WOC 18 hours. Test 15. Resumed drilling 6 16. Drilled to 3165'. 17. Ran DST #2 from 3 18. Drilled to 3571'.	ally drilled, give subsur le @ 10:00 pm 12-16 §", 36#, ST&C casin sing with 710 sacks ed BOP, casinghead 3/4" hole. 50'-3030'. 5. 20#, J-55, ST&C cas g with 220 sacks Pre Top of cement @ 11 sted BOP, casinghea 1/4" hole. 100'-3165'.	rface locations and m 93. 9 @ 1206' using 13 Premium Plus w/2% 1 and casing to 1000 and casing to 1000 mium Plus Light ce	easured and true centralizers. caci. Circ 150 s for 30 minutes for 30 minutes ment, tailed in w	vertical dep acks to su . Held OK vith 150 sa	oths for all markers and zones	
any proposed work. If well is direction pertinent to this work.) 1. Spudded 12 1/4" hol 2. Drilled to 1206'. 3. On 12-19-93 set 9 5// 4. Cemented 9 5/8" cas 5. WOC 18 hours. Test 6. Resumed drilling 8 7. Drilled to 3030'. 8. Ran DST #1 from 29 9. Drilled to 3100'. 10. Ran open hole logs 11. On 12-26-93 set 7"., 12. Cemented 7" casin 13. Ran temp. survey. 14. WOC 18 hours. Test 15. Resumed drilling 6 16. Drilled to 3165'. 17. Ran DST #2 from 3 18. Drilled to 3571'. 19. Ran open hole logs	ally drilled, give subsui le @ 10:00 pm 12-16 §", 36#, ST&C casin sing with 710 sacks ed BOP, casinghead 3/4" hole. 50'-3030'. 5. 20#, J-65, ST&C cas g with 220 sacks Pre Top of cement @ 11 sted BOP, casinghea 1/4" hole. 100'-3165'.	rface locations and m .93. g @ 1206' using 13 Premium Plus w/2% I and casing to 1000 and casing to 1000 90'. Ind and casing to 200	easured and true centralizers. caci. Circ 150 s for 30 minutes for 30 minutes ment, tailed in w	vertical dep acks to su . Held OK vith 150 sa	oths for all markers and zones	
any proposed work. If well is direction pertinent to this work.) 1. Spudded 12 1/4" hol 2. Drilled to 1206'. 3. On 12-19-93 set 9 5// 4. Cemented 9 5/8" cas 5. WOC 18 hours. Test 6. Resumed drilling 8 7. Drilled to 3030'. 8. Ran DST #1 from 29 9. Drilled to 3100'. 10. Ran open hole logs 11. On 12-26-93 set 7", 12. Cemented 7" casin 13. Ran temp. survey. 14. WOC 18 hours. Test 15. Resumed drilling 6 16. Drilled to 3166'. 17. Ran DST #2 from 3 18. Drilled to 3571'. 19. Ran open hole logs 20. T. D. of well 3671'.	ally drilled, give subsui le @ 10:00 pm 12-16 §", 36#, ST&C casin sing with 710 sacks ed BOP, casinghead 3/4" hole. 50'-3030'. 5. 20#, J-65, ST&C cas g with 220 sacks Pre Top of cement @ 11 sted BOP, casinghea 1/4" hole. 100'-3165'. 5. Released rig 12-31-4	rface locations and m 93. g @ 1206' using 13 Premium Plus w/2% and casing to 1000 and casing to 1000 mium Plus Light ce 90'. ad and casing to 200	centralizers. ccaci. Circ 150 s for 30 minutes 0 centralizers. ment, tailed in w	acks to su Acks to su Held OK	oths for all markers and zones	
any proposed work. If well is direction pertinent to this work.) 1. Spudded 12 1/4" hol 2. Drilled to 1206'. 3. On 12-19-93 set <u>9 5//</u> 4. Cemented 9 5/8" cas 5. WOC 18 hours. Test 6. Resumed drilling 8 7. Drilled to 3030'. 8. Ran DST #1 from 29 9. Drilled to 3100'. 10. Ran open hole logs 11. On 12-26-93 set 7", 12. Cemented 7" casin 13. Ran temp. survey. 14. WOC 18 hours. Test 15. Resumed drilling 6 16. Drilled to 3165'. 17. Ran DST #2 from 3: 18. Drilled to 3571'. 19. Ran open hole logs 20. T. D. of well 3571'. 21. Waiting on comple	ally drilled, give subsur le @ 10:00 pm 12-16 8", 36#, ST&C casin sing with 710 sacks ed BOP, casinghead 3/4" hole. 50'-3030'. 50'-30'. 5	rface locations and m 93. g @ 1206' using 13 Premium Plus w/2% and casing to 1000 and casing to 1000 mium Plus Light ce 90'. ad and casing to 200	centralizers. ccaci. Circ 150 s for 30 minutes 0 centralizers. ment, tailed in w	acks to su Acks to su Held OK	oths for all markers and zones	
any proposed work. If well is direction pertinent to this work.) 1. Spudded 12 1/4" hol 2. Drilled to 1206'. 3. On 12-19-93 set 9 5// 4. Cemented 9 5/8" cas 5. WOC 18 hours. Test 6. Resumed drilling 8 7. Drilled to 3030'. 8. Ran DST #1 from 29 9. Drilled to 3100'. 10. Ran open hole logs 11. On 12-26-93 set 7", 12. Cemented 7" casin 13. Ran temp. survey. 14. WOC 18 hours. Test 15. Resumed drilling 6 16. Drilled to 3166'. 17. Ran DST #2 from 3 18. Drilled to 3571'. 19. Ran open hole logs 20. T. D. of well 3571'. 21. Waiting on comple 14. I hereby certify that the foregoing is	ally drilled, give subsur le @ 10:00 pm 12-16 8", 36#, ST&C casin sing with 710 sacks ed BOP, casinghead 3/4" hole. 50'-3030'. 50'-30'. 5	rface locations and m 93. g @ 1206' using 13 Premium Plus w/2% and casing to 1000 and casing to 1000 mium Plus Light ce 90'. ad and casing to 200	centralizers. ccaci. Circ 150 s for 30 minutes 0 centralizers. ment, tailed in w	acks to su Acks to su Held OK	oths for all markers and zones	
any proposed work. If well is direction pertinent to this work.) 1. Spudded 12 1/4" hol 2. Drilled to 1206'. 3. On 12-19-93 set <u>9 5//</u> 4. Cemented 9 5/8" cas 5. WOC 18 hours. Test 6. Resumed drilling 8 7. Drilled to 3030'. 8. Ran DST #1 from 29 9. Drilled to 3100'. 10. Ran open hole logs 11. On 12-26-93 set 7", 12. Cemented 7" casin 13. Ran temp. survey. 14. WOC 18 hours. Test 15. Resumed drilling 6 16. Drilled to 3166'. 17. Ran DST #2 from 3: 18. Drilled to 3571'. 19. Ran open hole logs 20. T. D. of well 3671'. 21. Waiting on comple	ally drilled, give subsur le @ 10:00 pm 12-16 8", 36#, ST&C casin sing with 710 sacks ed BOP, casinghead 3/4" hole. 50'-3030'. 5. 20#, J-65, ST&C cas g with 220 sacks Pre Top of cement @ 11 sted BOP, casinghea 1/4" hole. 100'-3165'. 5. Released rig 12-31-4 tion unit. Estimate of true and correct	rface locations and m 93. g @ 1206' using 13 Premium Plus w/2% and casing to 1000 and casing to 1000 mium Plus Light ce 90'. ad and casing to 200	centralizers. Scaci. Circ 150 st acaci. Circ 150 st for 30 minutes 10 centralizers. Sment, tailed in w 20# for 30 minute 100# for 30 minute	vertical dep acks to su . Held OK with 150 sa . Held OK . Held OK	oths for all markers and zones	
any proposed work. If well is direction pertinent to this work.) 1. Spudded 12 1/4" hol 2. Drilled to 1206'. 3. On 12-19-93 set 9 5// 4. Cemented 9 5/8" cas 5. WOC 18 hours. Test 6. Resumed drilling 8 7. Drilled to 3030'. 8. Ran DST #1 from 29 9. Drilled to 3100'. 10. Ran open hole logs 11. On 12-26-93 set 7", 12. Cemented 7" casin 13. Ran temp. survey. 14. WOC 18 hours. Test 15. Resumed drilling 6 16. Drilled to 3165'. 17. Ran DST #2 from 3 18. Drilled to 3671'. 19. Ran open hole logs 20. T. D. of well 3571'. 21. Waiting on completing 14. I hereby certify that the foregoing is	ally drilled, give subsur le @ 10:00 pm 12-16 8", 36#, ST&C casin sing with 710 sacks ed BOP, casinghead 3/4" hole. 50'-3030'. 5. 20#, J-65, ST&C cas g with 220 sacks Pre Top of cement @ 11 sted BOP, casinghea 1/4" hole. 100'-3165'. 5. Released rig 12-31-4 tion unit. Estimate of true and correct 	rface locations and m 93. g @ 1206' using 13 Premium Plus w/2% and casing to 1000 imium Plus Light ce 90'. ad and casing to 200 93. completation operat	centralizers. Scaci. Circ 150 st acaci. Circ 150 st for 30 minutes 10 centralizers. Sment, tailed in w 20# for 30 minute 100# for 30 minute	vertical dep acks to su . Held OK with 150 sa . Held OK . Held OK	oths for all markers and zones inface.	
any proposed work. If well is direction pertinent to this work.) 1. Spudded 12 1/4" hol 2. Drilled to 1206'. 3. On 12-19-93 set 9 5/4 4. Cemented 9 5/8" cas 5. WOC 18 hours. Test 6. Resumed drilling 8 7. Drilled to 3030'. 8. Ran DST #1 from 29 9. Drilled to 3100'. 10. Ran open hole logs 11. On 12-26-93 set 7", 12. Cemented 7" casin 13. Ran temp, survey. 14. WOC 18 hours. Test 15. Resumed drilling 6 16. Drilled to 3165'. 17. Ran DST #2 from 3 18. Drilled to 3571'. 19. Ran open hole logs 20. T. D. of well 3671'. 21. Waiting on comple 14. I hereby certify that the foregoing is Signed: Que Cl. Jourb (This space for Federal or State office to	ally drilled, give subsur le @ 10:00 pm 12-16 §", 36#, ST&C casin sing with 710 sacks ed BOP, casinghead 3/4" hole. 50'-3030'. 5. 20#, J-55, ST&C cas g with 220 sacks Pre Top of cement @ 11 sted BOP, casinghea 1/4" hole. 100'-3165'. 5. Released rig 12-31-4 tion unit. Estimate of true and correct 	rface locations and m 93. g @ 1206' using 13 Premium Plus w/2% and casing to 1000 imium Plus Light ce 90'. ad and casing to 200 93. completation operat	centralizers. Scaci. Circ 150 st acaci. Circ 150 st for 30 minutes to centralizers. Sment, tailed in w 00# for 30 minute 100# for 30 minute	vertical dep acks to su . Held OK rith 150 sa . Held OK 28-94. Date	eths for all markers and zones	
any proposed work. If well is direction pertinent to this work.) 1. Spudded 12 1/4" hol 2. Drilled to 1206'. 3. On 12-19-93 set 9 5/4 4. Cemented 9 5/8" cas 5. WOC 18 hours. Test 6. Resumed drilling 8 7. Drilled to 3030'. 8. Ran DST #1 from 29 9. Drilled to 3100'. 10. Ran open hole logs 11. On 12-26-93 set 7", 12. Cemented 7" casin 13. Ran temp. survey. 14. WOC 18 hours. Test 15. Resumed drilling 6 16. Drilled to 3166'. 17. Ran DST #2 from 3 18. Drilled to 3571'. 19. Ran open hole logs 20. T. D. of well 3671'. 21. Waiting on comple 14. I hereby certify that the foregoing is Signed: Que Cl. Jack	ally drilled, give subsur le @ 10:00 pm 12-16 8", 36#, ST&C casin sing with 710 sacks ed BOP, casinghead 3/4" hole. 50'-3030'. 5. 20#, J-65, ST&C cas g with 220 sacks Pre Top of cement @ 11 sted BOP, casinghea 1/4" hole. 100'-3165'. 5. Released rig 12-31-4 tion unit. Estimate of true and correct 	rface locations and m 93. g @ 1206' using 13 Premium Plus w/2% and casing to 1000 imium Plus Light ce 90'. ad and casing to 200 93. completation operat	centralizers. Scaci. Circ 150 st acaci. Circ 150 st for 30 minutes to centralizers. Sment, tailed in w 00# for 30 minute 100# for 30 minute	vertical dep acks to su . Held OK with 150 sa . Held OK . Held OK	eths for all markers and zones	

or representations as to any matter within its jurisdiction.