

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 32372
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	B-9311
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	144
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3186', KB-3197'

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter J : 1400 Feet From The S Line and 1880 Feet From The E Line Section 32 Township 24S Range 38E NMPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3186', KB-3197'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Acidize & add perfs ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-03-99: MIRU. UNSEAT PUMP. NDWH. NUBOP. TIH W/BIT & CSG SCRAPER ON TBG TO 6476'. PULL BIT TO 4457'.
5-04-99: TIH W/CSG GUN & PERF DRINKARD FORMATION 6406-10, 6412-20, 6424-27, 6431-36'. TIH W/WRP & SET @ 6452'. TIH W/PKR, SN & TBG TO 1905'.
5-05-99: TIH W/TBG. TAG WRP @ 6452'. PULL PKR TO 6447'. TEST WRP TO 1000#-OK. PULL PKR TO 6334' & SET. ACIDIZE DRINKARD PERFS 6406-6436' W/5000 GALS 15% NEFE HCL. PULL PKR TO 6157'. PUMP 20 BBLs 2% KCL WTR DN CSG. PSA 6157'. RU SWAB. FL @ 650'. END FL @ 2200'. RU PUMP TRUCK. SCALE SQUEEZE SAME PERFS W/10 GALS TW-430 & 1 GAL ALPHA 133.
5-06-99: REL PKR. TIH W/RET TOOL ON TBG. LATCH & REL WRP @ 6452'. TIH W/OPSMA, SN, TBG. TBG TESTED TO 5000#. MA @ 6497'. SN @ 6467'. TAC @ 6171'. NDBOP. NUWH.
5-07-99: TIH W/GAS ANCHOR, PUMP & RODS. HANG WELL ON & LOAD & TEST TO 500 PSI-OK. NO PUMP ACTION.
5-08-99: RAN PUMP. LOAD & TEST-OK. CHECK PUMP ACTION. PUMPING. FOUND METAL IN PUMP. PUMPING @ 10:00 AM. RIG DOWN.
5-26-99: ON 24 HR OPT. PUMPED 48 BO, 445 BW, & 10 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 6/16/99
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS

APPROVED BY DISTRICT I SUPERVISOR TITLE DATE JUL 03 1999

CONDITIONS OF APPROVAL, IF ANY: