

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30 025 32373
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-9311
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	145
9. Pool Name or Wildcat	DOLLARHIDE; TUBB-DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3172', KB-3183'

**SUNDRY NOTICES AND REPORTS ON WELL**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>K</u> : <u>2589</u> Feet From The <u>SOUTH</u> Line and <u>2060</u> Feet From The <u>WEST</u> Line Section <u>32</u> Township <u>24-S</u> Range <u>38-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3172', KB-3183'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☒ ACIDIZE

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-01-99: MIRU. UNSET TAC & NUBOP.  
9-02-99: TIH W/SONIC HAMMER TOOL & WASH DRINKARD PERFS W/2% KCL WTR. ACIDIZE PERFS W/4000 GALS 15% NEFE. SWAB.  
9-03-99: TIH W/MUD JT, SN, TBG, TAC. SET TAC & ND BOP & FLANGE UP WH. TAC @ 6386'. SN @ 6832'. TBG @ 6830'. TIH W/PUMP, GAS ANCHOR, SNKR BARS & RDS. SPACE OUT & HANG ON. LOAD & TEST W/500 PSI-OK. RIG DOWN.  
9-30-99: ON 24 HR OPT. PUMPED 21 BO, 240 BW, & 22 MCF.  
FINAL REPORT.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 10/12/1999  
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)  
ORIGINAL SIGNED BY GARY WINK DATE OCT 18 1999  
APPROVED BY FIELD REP. II TITLE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: