

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. <b>30-025-32633</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>B-228-1</b>
7. Lease Name or Unit Agreement Name <b>SOUTH JUSTIS UNIT</b>
8. Well No. <b>295</b>
9. Pool name or Wildcat <b>JUSTIS BLBRY-TUBB-DKR</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator <b>ARCO Permian</b>	3. Address of Operator <b>P.O. BOX 1610, MIDLAND, TX 79702</b>
4. Well Location Unit Letter <b>D</b> : <b>1100</b> Feet From The <b>NORTH</b> Line and <b>300</b> Feet From The <b>WEST</b> Line Section <b>36</b> Township <b>25S</b> Range <b>37E</b> NMPM <b>LEA</b> County		
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <b>3029 GR</b>		

11.

**Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☒  
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD'D 7 7/8 HOLE AT 6200 ON 09-10-94. RAN OH LOGS. RIH W/ 4 1/2 10.5# CSG. PIPE SET DOWN AT 6068. PULL UP TO 6041. PIPE STUCK & WOULD NOT CIRC. RAN FREE POINT. PARTIAL STUCK @ 5870. 100% STUCK @ 5950. CMTED 4 1/2 CSG @ 6041 W/150 SX C + 12# CSE + 1# WL-1P + .3%CF-2 + 1/4# FC + 3# HI-SEAL. DID NOT CIRC CMT. PERF 4 1/2 CSG @ 5900. COULD NOT PUMP INTO. RAN BOND LOG F/5972-4700. PERF @ 5850. PUMPED INTO PERFS BUT WOULD NOT CIRC. PUMPED 150 SX "C" CMT + SAME ADD. (YLD 1.83). DISPLACED TO 3082 & LOCKED DOWN @ 2800#. RR 09-12-94.

10-04-94. RUPU. DRILL OUT CMT F/3012-5861. ISOLATE TEST SQZ PERFS @ 5850 TO 500# FOR 30 MIN. DO CMT F/5875-5928. ISOLATE TEST SQZ PERFS @ 5900 TO 500#. LOST 380# IN 10 MIN. RAN CBL F/6008-900. TOC @ 5750. SET CIBP @ 5800. PERF 4 1/2 CSG @ 5060. ESTAB CIRC. CMT"D W/600 SX C NEAT. WOC OVER NIGHT. DO CMT F/4903-5064. WASH TO 5154. PRESS TEST CSG TO 1000#. RAN CBL F/5765-2580. TOC @ 2940. DO CIBP. PERF BTD F/5050-5880. A W/10,000 GALS. RIH W/CA 2 3/8 TBG, RODS & PUMP TO 5892. RDPU 10-18-94.

10-24-94. In 24 hrs pmp'd 84 BO, 143 BW, 119 MCF

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ken W. Gosnell TITLE AGENT DATE 10-26-94

TYPE OR PRINT NAME KEN W. GOSNELL TELEPHONE NO. 915 688-5672

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE OCT 28 1994

CONDITIONS OF APPROVAL, IF ANY: