

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OF CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30 025 32768

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil / Gas Lease No.

7. Lease Name or Unit Agreement Name

WEST DOLLARHIDE DRINKARD UNIT

8. Well No.

111

9. Pool Name or Wildcat

DOLLARHIDE TUBB DRINKARD

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI
(FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
15 SMITH ROAD, MIDLAND, TX 79705

4. Well Location
Unit Letter K : 1360 Feet From The SOUTH Line and 2055 Feet From The WEST Line
Section 32 Township 24-S Range 38-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3162'-GR, 3175'-KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: CLEAN OUT, ACIDIZE, RETURN TO PROD ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

THE SUBJECT WELL WILL BE CLEANED OUT, ACIDIZED, AND RETURNED TO PRODUCTION. THE INTENDED PROCEDURE IS AS FOLLOWS:

- 1) INSTL BOP. REL TAC.
- 2) TIH W/BIT & BAILER & C/O TO PBTD @ 6815'.
- 3) TIH W/CSG SCRAPER TO 6440'.
- 4) TIH W/RBP & PKR. SET RBP ON BOTTOM. PULL UP & SET PKR @ 6400.
- 5) DO NOT LOAD CASING. MONITOR PRESSURE WHILE ACIDIZING.
- 6) RU ACID TRUCK. ESTAB RATE. SCALE SQZ UNDER PKR.
- 7) REL PKR & LOWER TO RBP ON BOTTOM. LATCH ON & PULL UP & SET @ 6300. PULL UP TO 6050 & SET PKR.
- 8) RU ACID TRUCK. ESTAB RATE. SCALE SQZ UNDER PKR.
- 9) REL PKR & LOWER TO RBP @ 6300. LATCH ON & RELEASE.
- 10) TIH W/ONE 3" MA, SN. PLACE SN @ 6720. TAC @ 6000.
- 11) TIH W/PMP & RDS. PLACE ON PRODUCTION & MONITOR TEST FLUID LEVEL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Regulatory Specialist

DATE 1/28/02

Telephone No. 915-687-7375

TYPE OR PRINT NAME J. Denise Leake

(This space for State Use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY: TITLE

ORIGINAL SIGNED BY
PAUL F. KAUTZ
PETROLEUM ENGINEER

DATE FEB 04 2002

Desoto/McCormick 12-0000

5
C