Form 3160-5 (June 1990)

APPROVED

BUNDITIONS OF APPROVAL IF ANY:

representations as to any matter within its jurisdiction.

_TITLE

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or

IED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

Budget Bureau No. 1004-0135

DUNEAU U	F LAND WANAGEWENT	===g=: ==:saa 110; 1004:0100
		Expires: March 31, 1993
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		5. Lease Designation and Serial No.
		NMLC 057509
	FOR PERMIT" for such proposals	6. If Indian, Alottee or Tribe Name
USE APPLICATION	FOR PERMIT — for such proposals	=
SUBM	MIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
1. Type of Well: OIL — GAS — OTHER 2. Name of Operator		Well Name and Number
		Erwin, G. L. "B" Federal NCT-2
TEXACO EXPLOR	ATION & PRODUCTION INC.	7
3. Address and Telephone No. PO BOX 3109, MI	DLAND, TX 79702 915-688-475	9. API Well No.
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		30 025 32949
Unit Letter O : 990 Feet From T	he SOUTH Line and 2250 Feet From The	Field and Pool, Exploaratory Area Langlie Mattix Seven River Queen Grayburg
EAST Line Section 35	Township 24S Range 37E	11. County or Parish, State
	Name 3/E	LEA , NEW MEXICO
12. Check Appropriate	Box(s) To Indicate Nature of Notice, Re	eport, or Other Data
TYPE OF SUBMISSION	TYPE OF ACTION	
	Abandonment	Change of Plans
_	Recompletion	New Construction
✓ Notice of Intent	Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair	-
Final Abardonment Notice	Atlering Casing	Water Shut-Off Conversion to Injection
	✓ OTHER: RECOMPLETION	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)
ChevronTexaco intends to recomplete the subject 1) TREAT PROD EQPT TO REMOVE PARAFIED MIRU PU. TOH W/RDS & PMP. INSTL; BOY 3) IRU WL & SET CIBP @ 5000°. TOP W/35° CONTRIBUTED VERIFY THAT IT IS POSSIBLE TO ABANDON 4) RUN GR CORRELATION LOG TO GET ON 5) PERF GRAYBURG 3472-76°, 3484-94°, 350° TIH W/TBG & PKR. 7) ACIDIZE PERFS W/2000 GALS 20% NEFE	P. TOH W/TBG. RUN BIT & SCRAPER TO 5000'. MT & TEST TO OCD FOR ZA STATUS OF THE BLINE ALL ZONES AT ONCE OR VERIFY THE NEED TO SE DEPTH WITH SPECTRAL DENSITY DUAL SPACED I 2-04'. HCL & BALL SEALERS DUND, CMT SQUEEZE PERFS, DRILL OUT & RETUR	burg.The intended procedure is as follows: EBRY/TUBB/DRINKARD. (WILL NEED TO INDIVIDUAL PLUGS). NEUTRON SPECTRAL GAMMA LOG.
an Allan	OPER. OGRID NO. 22351	
"Elitaria"	PROPERTY NO. 19131	~
100 minor	POOL CODE 37240	
162 XW. O. V.	FORM COUNTY	
EXP PLUX	EFF. DATE	mi L
10 13 O. C.	APINO. 025-32949	"
) ^c	•	
14. I hereby certify that the foregoing is true Alto correct		
SIGNATURE A LAUSE	Makeurle Engineering Assistant	DATE 11/14/01
TYPE OR PRINT NAME J. Denis	e Leake	
(This space for Federal or State office use)		

DATE