

Submit 3 copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.

30 025 33168

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil / Gas Lease No.

7. Lease Name or Unit Agreement Name

NEW MEXICO 'BZ' STATE NCT-10

8. Well No.

6

9. Pool Name or Wildcat

JUSTIS; BLINEBRY, TUBB DRINKARD

SUNDRY NOTICES AND REPORTS ON WELL  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator: TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator: 205 E. Bender, HOBBS, NM 88240

4. Well Location

Unit Letter N 480 Feet From The SOUTH Line and 1650 Feet From The WEST Line

Section 2 Township 25S Range 37E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3132 GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☒ STIM W/ACID & SCALE SQZ

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-19-98: MIRU. POH W/RDS & PMP. SCALE ON PUMP. NUBOP & TAG DN W/TBG @ 6210'.

11-20-98: TIH W/BAILER & C/O FILL FR 6210-PBTD @ 6311'. TOH W/BAIKLER. TIH W/SONIC HAMMER TOOL & ACIDIZE PERFS 5364-6216' W/3500 GALS 15% 60/40 IAD ACID. DROP BALL & OPEN SHEAR SLEEVE.

11-21-98: SWAB BACK LOAD. TOH W/HAMMER TOOL. TIH W/PROD TBG. NDBOP & FLANGE UP WH. TIH W/PMP & RDS. PLACE C/N PROD.

11-23-98: RIG DOWN.

11-27-98: MIRU. PULL PMP & SENT TO PMP SHOP. SWAB WELL FOR 3 1/2 HRS. RAN PUMP BACK & PLACED ON PUMP. RIG DOWN.

12-01-98: APPLIED BACK PRESSURE TO CSG. (55 PSI).

12-13-98: ON 24 HR OPT. PUMPED 10 BO, 20 BW, & 13 MCF. GOR-650.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 1/7/99

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: