

**DISTRICT I**

P.O. Box 1980, Hobbs, NM 88240

**DISTRICT II**

P.O. Box Drawer DD, Artesia, NM 88210

**DISTRICT III**

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33401
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-1732
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	153
9. Pool Name or Wildcat	DOLLARHIDE: TUBB-DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3177'

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.	
1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	CHEVRON USA INC
3. Address of Operator	15 SMITH ROAD, MIDLAND, TX 79705
4. Well Location	Unit Letter <u>M</u> : <u>1150</u> Feet From The <u>SOUTH</u> Line and <u>800</u> Feet From The <u>WEST</u> Line Section <u>33</u> Township <u>24-S</u> Range <u>38-E</u> NMPM <u>LEA</u> COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3177'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐ FRACTURE TREATMENT ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-30-02: MIRU.  
7-31-02: REL TAC. TIH W/BIT & SCRAPER TO 6720. SET CIBP @ 6670. TIH W/PKR.  
8-01-02: SET PKR @ 6660. TEST CIBP TO 500# - 30 MIN-OK. REL PKR. PERF DRINKARD @ 6486-6500M 6504-08, 6513-22, 6532-62, 6566-76, 6580-86, 6600-02, 6610-13. TIH W/SONIC HAMMER. (CHART ATTACHED)  
8-02-02: SONIC HAMMER TO 6486. ACIDIZE WASH W/3000 GALS 15% NEFE HCL FR 6486-6613. RU SWAB.  
8-05-02: SET PKR @ 6100. TP @ 6442.  
8-06-02: FRAC W/YF140 & 20/40 CARBO-LITE, & 14,000 GALS YF140.  
8-07-02: REL PKR.  
8-08-02: TIH W/BAILER. TAG @ 6530. TIH & TAG NO FILL. TIH W/SN, TAC, 192 JTS. TRY TO SET TAC. WILL NO SET.  
8-09-02: PMP 20 BBLS WTR DN BACKSIDE. WILL NO SET. EOT-6597. TAC @ 6025. RAN GAS ANCHOR, K-BARS, SUBS. REPLACE BOXES. LOAD & TEST TBG.

**FINAL REPORT**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Denise Leake TITLE Regulatory Specialist DATE 10/1/2002  
TYPE OR PRINT NAME Denise Leake Telephone No. 915-687-7375

(This space for State Use)

APPROVED  
CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY  
GARY WEWINK  
OC FIELD REPRESENTATIVE II/STAFF MANAGER

DATE

OCT 18 2002

DeSoto/Nichols 12-93 ver 1.0