

Submit 3 copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33402
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-9311
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	154
9. Pool Name or Wildcat	DOLLARHIDE TUBB-DRINKARD

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter _____ : _____ 2575 Feet From The SOUTH Line and 625 Feet From The EAST Line Section 32 Township 24-S Range 38-E NMPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3182'

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Acidize & Scale Squeeze ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-26-99: TIH W/SONIC HAMMER TOOL & ACIDIZE W/1000 GALS 15% NEFE. BLED OFF WELL & TOH W/SONIC HAMMER TOOL. TIH W/PKR & SET @ 6450'.
1-27-99: ACIDIZE DRINKARD W/1000 GALS 15% NEFE W/1/2 PPG 100 MESH SALT. STARTED FLOWING BACK. SWAB. FL @ 800'. END FL @ 3000'. SCALE SQUEEZE W/2 DRUMS TH793 IN 20 BBLs 2% KCL WATER & FLSH W/200 BBLs PROD WATER.
1-28-99: UNSET PKR & TOH. TIH W/MUD JOINT, SN, TBG, & TAC. SN @ 6647'. TAC @ 6424'. NDBOP & SET TAC. FLANGE UP WELL & TIH W/GAS ANCHOR, PUMP, SNKR BARS & RDS. SPACE OUT & HANG ON.
1-29-99: RIG DOWN.
2-03-99: ON 24 HR OPT. PUMPED 20 BO, 247 BW, & 4 MCF. GOR-200. PERFS: 6480-6605' DRINKARD
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 3/18/99
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for Stamp)
ORIGINAL SIGNED BY CHRIS WILLIAMS
APPROVED BY DISTRICT I SUPERVISOR TITLE _____ DATE MAR 31 1999

CONDITIONS OF APPROVAL, IF ANY: