

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33404
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	157
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3133'	

SUNDY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator
205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter P : 1275 Feet From The SOUTH Line and 400 Feet From The EAST Line
Section 31 Township 24-S Range 38-E NMPM LEA COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPERATION ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-27-97: MIRU. INSTL BOP. TAG BTM @ 6925'.

10-28-97: RAN BIT & CSG SCRAPER ON TBG. SCRAPE PERFS 6376-6880'. TAG BTM @ 6925'.

10-29-97: RAN SONIC HAMMER ON TBG. WSHD & ACIDIZED PERFS, DRINKARD ZONE 6376-6499' & ABO ZONE 6586-6880' W/283 BBLS 2% KCL FW & 5000 GALS 15% NEFE THRU SONIC HAMMER. FLSH W/37 BBLS 2% KCL FW.

10-30-97: RAN RBP, PKR, & SN. TEST @ 10,000 PSI. SET RBP @ 6540'.

10-31-97: KILL WELL. PSA 6534'. TET RBP TO 2500#. OK. RESET PKR @ 6258'. LOAD ANNULUS W/19 BBLS 2% KCL FW.

11-03-97: INSTL TREE SAVER. PRESS ANN TO 1000#. FRAC 6376-6499', DRINKARD, W/29,500 GALS OF 40# X-LNKD GEL.REM TREE SAVER & INSTL TIW VALVE.

11-04-97: TIH W/SINKER BAR TO PKR @ 6258'. NO SAND. UNSET PKR. TIH W/BIT & TBG.

11-05-97: TIH W/BIT ON BAILER & TBG. TAG SAND FILL @ 6433'. C/O SD TO 6529'.

11-06-97: TIH W/PKR ON TBG. PSA 6297'. SCALE SQUEEZE DRINKARD PERFS 6376-6499 W/110 GALW TH-793.

11-07-97: REL PKR. TIH W/MA, SN, TBG, TAC. SET @ 15' KB, BMT OF MA @ 6490'. SN @ 6457'. TAC @ 6265'. NDBOP. NUWH. TIH W/PUMP. WELL PUMPING @ 4:30 PM.

11-10-97: RD.

11-11/11-18-97: TESTING

11-18-97: ON 24 OPT. PUMPED 36 BO, 11 BW, & 21 MCFPD. CHANGE STATUS FR WO TO PUMPING-OIL.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief

SIGNATURE J. Denise Leake TITLE Engineering Assistant

DATE 1/20/98

TYPE OR PRINT NAME J. Denise Leake

Telephone No. 397-0405

(This space for State Use)

ORIGINAL SIGNATURE, EMPLOYER'S WILL BE REQUIRED
DISTRICT

APPROVED BY _____ TITLE _____

DATE SEP 28 1999

CONDITIONS OF APPROVAL, IF ANY: