

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-33803
5. Indicate Type of Lease <i>Federal</i> STATE ☐ FEE ☐	
6. State Oil / Gas Lease No.	LC-057509
7. Lease Name or Unit Agreement Name <i>ERWIN G. L. - B. NCT-2</i> <i>Federal</i>	
8. Well No.	10
9. Pool Name or Wildcat <i>Justis</i> JUSTIS BLINEBRY TUBB DRINKARD	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3159 GL

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u> </u> : <u> </u> 2450 Feet From The <u> </u> SOUTH Line and <u> </u> 1225 Feet From The <u> </u> EAST Line Section <u> </u> 35 Township <u> </u> 24-S Range <u> </u> 37E NMPM <u> </u> LEA COUNTY
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3159 GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☒	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPERATION ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER: ☐	CASING TEST AND CEMENT JOB ☐	ACIDIZE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-02-99: MIRU. KILL WELL W/40 BBLS 2% KCL. UNSEAT PUMP. NDWH. NUBOP. TIH W/BIT & CSG SCRAPER TO 1896'.
9-03-99: TAG @ 6282'.
9-04-99: TIH W/PERF GUN & PERF DRINKARD FORMATION 6115,16,18,19,24,25,26. PERF BLINEBRY FORMATION 5030-36,5050-54,5056-60,5063-65,5068-73. TIH W/PKR. SET RBP ON TBG. ATTEMPT TO SET RBP 5088,81,90,- WOULD NOT HOLD. TIH W/TBG TO 1896'.
9-07-99: PUMP 15 BBLS DN TBG & CSG TO KILL WELL. TIH W/WRP & SET @ 5085'. TIH W/PKR, SN ON TBG. PSA 4969'. LOAD & TEST BACKSIDE TO 500#-OK. ACIDIZE BLINEBRY CSG PERFS 5030-73' W/4000 GALS 15% NEFE HCL & 2000# RK SLT. RU SWAB. FL @ 3400'. END FL @ 3200'.
9-08-99: KILL WELL W/30 BBLS 2% KCL WTR. REL PKR. TIH W/RET TOOL ON TBG. TAG 5078'. WASH 8' RK SLT OFF TOP OF RBP. LATCH & REL WRP @ 5085'. TIH W/PURGE VALVE, SN, TBG, TAC. STOP TBG @ 2400'.
9-09-99: KILL WELL W/20 BBLS 2% KCL. TIH W/TBG. MA @ 6227'. SN @ 6175'. TAC @ 4973'. NDBOP. NUWH. TIH W/GAS ANCHOR, PUMP, SNKR BARS, RDS.
9-10-99: LOAD & TEST TO 500 PSI. RIG DOWN.
10-10-99: ON 24 HR OPT. PUMPED 21 BO, 10 BW, & 375 MCF.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 10/12/1999

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

ORIGINAL SIGNED BY GARY WINK

APPROVED BY FIELD REP. TITLE DATE

CONDITIONS OF APPROVAL, IF ANY:

