Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
District I	Energy, Minerals and Natural Resources		Revised March 25, 1999 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 District II			30-025-09629	
811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	2040 South Pacheco		STATE FEE	
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
2040 South Pacheco, Santa Fe, NM 87505				
	TICES AND REPORTS ON WELL		7. Lease Name or	r Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Gaaran Ta	1 !!!!
PROPOSALS.)			Cooper Ja	1 Unit
1. Type of Well: Oil Well ₩ Gas Well	Other			
2. Name of Operator			8. Well No.	
Texaco Exploration & Production, Inc.			204	
3. Address of Operator			9. Pool name or Wildcat	
P. O. Box 3109, Midland, TX 79702 4. Well Location			Jalmat, Tansill, Y, 7 Rvrs	
- Wen Education				
Unit Letter F :	: 1980 feet from the Nort	h line and	1980 feet from	n the <u>West</u> line
Santian	T	D 26E	NUMBER TOO	
Section 24	Township 24S 10. Elevation (Show whether	Range 36E	NMPM Lea	County
	To: Elevation (Show Witchie)	DN, 100, N1, O1, 6	10.)	
11. Check	Appropriate Box to Indicate	Nature of Notice,	Report or Other I	Data
NOTICE OF I	NTENTION TO:	SUE	SEQUENT REI	PORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WOR	RK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	RILLING OPNS.	PLUG AND
PULL OR ALTER CASING MULTIPLE CASING TEST A			ND	ABANDONMENT -
	COMPLETION	CEMENT JOB	لسيبا	
OTHER:		OTHER:		
12. Describe proposed or comp	oleted operations. (Clearly state a	II pertinent details, a	nd give pertinent date	es, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompilation. 1. Set 5 1/2" CIBP @ 2980 (Jalmat) - Dump 35 of CMT, 4 TAG				
1. Set 5 1/2" CIBP @ 2980 (Jalmat) DUMP 30 of CMI THE 2. Spot 30 Sx plug 2980-2700 (Yates-B-Salt) WOC Tag				
3. Displace hole w/MLF 9.5# Brine w/25# gel P/BBL				
4. Spot 25 Sx plug 1300-1100 (T-Salt) WOC Tag				
5. Fill 5 1/2" Csg w/40 Sx Cmt 350-Surf				
6. Install dry hole marker				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE /. C	all TITL	E FACILITY E	NGR	DATE_///7/00
Type or print name / AMES	3 T. CORBITT		T-1	phone No. 688-4438
(This space for State use)	5 (ı elep	mone No. 600 779
				NOV & 2000
APPPROVED BY	TITLE	Landard Company of the Company of	- 1	_DATEO_LININ
Conditions of approval, if any:			* •	
		Charles To His		\mathcal{O}

ر 2

MP

234567867 Section of the section of