

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name <u>Cooper Jal Unit</u>
2. Name of Operator <u>Texaco Producing Inc.</u>		8. Farm or Lease Name
3. Address of Operator <u>P.O. Box 728 Hobbs, NM 88240</u>		9. Well No. <u>231</u>
4. Location of Well UNIT LETTER <u>H</u> <u>1650</u> FEET FROM THE <u>North</u> LINE AND <u>330</u> FEET FROM THE <u>East</u> LINE, SECTION <u>25</u> TOWNSHIP <u>24S</u> RANGE <u>36E</u> NMPM.		10. Field and Pool, or Wildcat <u>Jalmat T-Y-SR</u>
15. Elevation (Show whether DF, RT, GR, etc.) <u>3285 DF</u>		12. County <u>Lea</u>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☒	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work); SEE RULE 1103.

1. Pull production equipment. Set CIBP at 1100'.
2. Squeeze 5 1/2" casing leak at 225' to 255' w/ 13 sk. Class C cement w/ 2% CaCl at low pressure. Shut-in 24 hours. Test to 200 psi.
3. Drill out cement & test 5 1/2" casing to 200 psi. Resqueeze and retest as required. Drill out CIBP at 1100'.
4. TTH w/ tubing and packer. Set packer at 2950'. Acidize Jalmat openhole 3002' to 3192' w/ 4500 gals 15% NEFE HCl acid. Swab back.
5. Frac the Jalmat openhole w/ 32,000 gal. x-link gelled water and 62,500 lb. 12/20 sand.
6. Cleanout as needed, rerun production equipment and pump well to test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>KL Johnson</u>	TITLE <u>AREA SUPERINTENDENT</u>	DATE <u>JAN 7 1988</u>
Orig. Signed by <u>Paul Kautz</u> Geologist	TITLE	DATE <u>JAN 11 1988</u>
APPROVED BY	TITLE	DATE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JAN 8 1983

OCJ
HOBBS OFFICE