## State of New Mexico Minerals and Natural Resources Department Ene

Forta C-103

Revised 1-1-89

DISTRICT II P.O. Box 1980, Hobbs, NM 88240  P.O. Box 2088  DISTRICT II P.O. Drawer DD, Artesia, NM 88210  DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410  SUNDRY NOTICES AND REPORTS ON WELLS  WELL API NO. 30-025-09695  5. Indicate Type of Lease STATE  6. State Oil & Gas Lease No.	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210  STATE  DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410  SUNDRY NOTICES AND REPORTS ON WELLS	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410  SUNDRY NOTICES AND REPORTS ON WELLS  5. Indicate Type of Lease STATE  6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd., Aziec, NM 87410  6. State Oil & Gas Lease No.  SUNDRY NOTICES AND REPORTS ON WELLS	7
SUNDRY NOTICES AND REPORTS ON WELLS	FEE X
SUNDRY NOTICES AND REPORTS ON WELLS	
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  7. Lease Name or Unit Agreement Name	2
(FORM C-101) FOR SUCH PROPOSALS.)	
i. Type of Well:	
WELL WELL STORMER Everett	
2. Name of Operator 8. Well No.	
Convest Energy Corporation 2  3. Address of Operator 9. Pool name or Wildcat	
2401 Fountain View Dr. Suite 700: Houston TV 77057	:
4. Well Location	
Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West	Line
Section 35 Township 24S Range 36E NMPM Lea	
Section Township 245 Range 36E NMPM Lea  ///////////////////////////////////	County
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF	
DEDECON DELIFICIAL MODIFICATION OF THE PROPERTY OF THE PROPERT	_
The state of the s	· <u> </u>
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABAND	ONMENT X
PULL OR ALTER CASING CASING TEST AND CEMENT JOB	
OTHER:OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.	i i
TOTAL TOTAL TOTAL	
3-10-95 ND wellhead. POOH w/ 2-3/8" tbg & submersible pump cable. NU wellhead & SD for weekend.	
to the meaning of the meaning of the meaning of the meaning of the meaning.	
3-13-95 RIH w/ tbg-set CIBP;' set @ 3200'. Packed off wellhead & circulated hole w/ mud; pumped 25 sx C cmt on to	
3200'-3050'. Perforated 4 holes @ 1502'; RIH w/ AD-1 packer to 1200'. Loaded hole & set packer, established	i rate @
2.5 BPM, 750#. Squeezed 45 sx C cmt 1502'-1457'.	
3-14-95 RIH & tagged plug @ 1348'; ok as per Gary Wink, Oil & Gas commission. Perforated 4 holes @ 50'. Set page	ker &
Set par	t &
squeezed 30 sx C cmt 50'-surface. Cut off wellhead, capped well, installed Dry Hole Marker. Covered working	
squeezed 30 sx C cmt 50'-surface. Cut off wellhead, capped well, installed Dry Hole Marker. Covered workpicellar. RDMO.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	15
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Cellar. RDMO.  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  Signature	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.  Signature	
Cellar. RDMO.  I hereby certify that the information above is true and complete to the best of my knowledge and belief.  SIGNATURE	