

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

NMLCO32618A

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE

7. If Unit or CA, Agreement Designation

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Convest Energy Corporation

3. Address and Telephone No.

2401 Fountain View Dr., Suite 700, Houston, TX 77057

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

600' FNL & 1980' FEL, Sec 35, T24S, R36E
660

8. Well Name and No.

I.B. Ogg A #2

9. API Well No.

300250970100S1

10. Field and Pool, or Exploratory Area

Jalmat T-15R

11. County or Parish, State

Ica County, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment☐ Recompletion☐ Plugging Back☐ Casing Repair☐ Altering Casing☐ Other☐ Change of Plans☐ New Construction☐ Non-Routine Fracturing☐ Water Shut-Off☐ Conversion to Injection☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

PLUGGING PROCEDURE

1. Notify BLM of Plugging, PRIOR TO ANY WORK, AT (505) 393-3612.

2. MI&RU Rig. POH w/ production eqpt, LD everything except tubing.

3. GIH & set CIBP @ 3,270'. Spot 50' cement on top of CIBP.

4. Spot cement plugs as below. Circ 9.0 ppg mud in intervals between plugs.

PERFORATE AS NECESSARY TO PLACE THE FOLLOWING PLUGS:
Cement plug from 2450' to 2350' 1725' - 1625' INSIDE AND OUTSIDE THE 7" CSG.
from 1400' to 1300' 219' - 119' INSIDE THE 7", 9 5/8", AND 12 1/2" CSGS. TAG
from 100' to surface. PLUG

Circulate or pump cement from 100' to surface in all casing annuli.

5. Cut off all casings 4' below ground level, weld on 1/2" steel plate with marker. Backfill and restore location.

14. I hereby certify that the foregoing is true and correct

Signed

Robert A. Kelly

Title

Sr. Petroleum Engineer

Date

8/20/91

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Approved by

Date

9/23/91

Well: I.B. Ogg A #2
Formation: Seven Rivers
TD: 3541' PBD 3358'
Elevation: 3287 D.F.

