-

## NEW MEXICO STATE LAND OFFICE SANTA FE, NEW MEXICO

## DEPARTMENT OF THE STATE GEOLOGIST

## NOTICE OF TEST OF WATER SHUT-OFF

Notice must be given to the State Geologist or to the proper Oil and Gas Inspector at least five days before the test. It is desirable that a representative of the Department of the State Geologist witness the water shut-off before drilling into the productive sand whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to sender. Submit this notice in duplicate.

ír. <b>E. H. Vells</b>			•		19 <b>.55</b>
State Geologist, Santa Fe, New Mexico.					
Dear Sir:				<b>z</b>	
You are hereby notified that we inte					
Vell No. <b>1</b> in of Se					
I. M. P. M., Jal, N. Mex					
n <b>Key 22nd</b> 19 <b>35</b> .	lb. casi	ng was ) ra (cen	nented (	in <b>14</b>	
ormation at a depth of <b>3254</b>	feet on	Ney 2	4 <b>th</b>	•••••	19 <b>55</b>
100 sacks of Incor		cement w	ere used.		
The method used in placing the cer	ment was as foll	lows:			
Hallibarton Plug Method					
		••••••	·····		••••
Additional information: In running 7" 0.D. Casing stud semented with 100 sacks Incor and semented back to 2000* wi	cement - then	run 5g 0.D.	to 3420	•	10 -
In running 7" 0.D. Casing stud semented with 100 sacks Incor	cement - then	run 5g 0.D.	to 3420	•	IC -
In running 7" 0.D. Casing stud semented with 100 sacks Incor	coment - then th Incor Comen	run 52" O.D.	to <b>3420</b>	)• 	€~S
In running 7" 0.D. Casing stud Genented with 100 sacks Incor and semented back to 2000' wi	cement - then th Incer Cemen 19 Sincere	run 52" 0.D.	to <b>3420</b>	e Go	
In running 7" 0.D. Casing stud Gemented with 100 sacks Incor and semented back to 2000' wi	cement - then th Incer Cemen 19 Sincere	run 52" 0.D.	to <b>3420</b>	e Go	
In running 7" O.D. Casing stud Genented with 100 sacks Incor and semented back to 2000' wi	coment - then th Incer Comen 19 Sincere By A.	run 52" 0.D.	to 3420	e Go	
In running 7" 0.D. Casing stud semented with 100 sacks Incor and semented back to 2000' wi	coment - then th Incer Comen 19 Sincere By J. Position	run 52" 0.D.	to 3420	Company or	
In running 7" 0.D. Casing stud semented with 100 sacks Incor and semented back to 2000' wi	coment - then th Incer Comen 19 Sincere By J. Position Send co	run 52" 0.D.	to 3420	Company or well to	· Operator.
In running 7" 0.D. Casing stud Genented with 100 sacks Incor and semented back to 2000' wi	coment - then th Incor Comen 19 Sincere By Jon Position Send co Name	run 52" 0.D.	to 3420	Company or well to	· Operator.
In running 7" 0.D. Casing stud Genented with 100 sacks Incor and semented back to 2000' wi	comment - then th Incor Comment 19	run 52" 0.D.	to 3420	Company or well to	