

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.O.S. | |
| LAND OFFICE | |
| OPERATOR | |

| | |
|--------------------------------|---|
| 5a. Indicate Type of Lease | |
| State <input type="checkbox"/> | Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No. | |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

| | | |
|---|-----------------------------------|---------------------------------|
| OIL WELL <input checked="" type="checkbox"/> | GAS WELL <input type="checkbox"/> | OTHER- <input type="checkbox"/> |
| 2. Name of Operator ARCO Oil & Gas Company Division of Atlantic Richfield Company | | |
| 3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240 | | |
| 4. Location of Well UNIT LETTER M 660 FEET FROM THE West LINE AND 660 FEET FROM THE South 6 LINE, SECTION 24S RANGE 37E NMPM. | | |

| |
|---|
| 7. Unit Agreement Name |
| 8. Farm or Lease Name Jim Camp WN |
| 9. Well No. 1 |
| 10. Field and Pool, or Wildcat Langlie Mattix 7 R Qn |
| 12. County Lea |

| |
|--|
| 15. Elevation (Show whether DF, RT, GR, etc.) 3341' |
|--|

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

| | |
|--|---|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input checked="" type="checkbox"/> Deepen, run liner, cmt, perf, acidize & treat same zone |

SUBSEQUENT REPORT OF:

| | |
|---|---|
| REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| COMMENCE DRILLING OPS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| CASING TEST AND CEMENT JOB <input type="checkbox"/> | OTHER <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Install BOP. POH w/ comp assy.
2. Run CBL, circ cmt behind 7" OD csg as determined from log.
3. Deepen from 3656-3750'. Run OH logs (GR-FDC-CNL-Caliper, GR DLL) 3246-3750' & GR-CNL log 1500-3750'. RIH w/ 4½" OD csg f/liner. Set liner 3150-3750' & cmt w/ C1 "C" cmt cont'g 2% CaCl. Perforate L-M zone from logs.
4. Perforate & acidize w/ 15% HCL acid & frac treat if necessary. Return to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. P. [Signature]

TITLE Dist. Drlg. Supt.

DATE 7/7/80

DATE SIGNED BY
JERRY BEATON

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

JUL 9 1980