

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Federal ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Salt Water Disposal	7. Unit Agreement Name
2. Name of Operator AMOCO PRODUCTION COMPANY	8. Farm or Lease Name Fowler Salt Water Disposal System
3. Address of Operator P. O. Box 68, Hobbs, New Mexico 88240	9. Well No. 1
4. Location of Well UNIT LETTER I 1650 FEET FROM THE South LINE AND 660 FEET FROM THE East LINE, SECTION 9 TOWNSHIP 24-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 3293' RDB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER Repair casing leak and acid. ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to run 5-1/2" casing and acidize as follows:

RIH with retrievable bridge plug and set at 1500'. Cap with 10' sand. RIH with packer and set at 30'. Run tubing and pump down tubing with 100 sx thickset cement followed by 200 sx class C with additives. Flush with produced water. Release packer. POH and WOC. Drill out cement, test squeeze to 500 PSI and circulate sand off RBP and POH. Release retrievable bridge plug. RIH with cast iron bridge plug and set at 3800'. Run tubing and packer. Run casing to 3790'. Cement with 800 sx class C neat. Circulate apx. 200 sx. DO cement and cast iron bridge plug to 3800'. RIH with packer and set at 3750'. Acid with 1000 gals 15% NE HCL with 2 gals NE/1000 gals acid. MOSU.

0+5-NMOCD,H 1-J. R. Barnett, HOU 21.156 1-F. J. Nash, HOU Rm. 4.206 1-BFC

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Bonita Goble TITLE Administrative Analyst DATE 8-20-84

Eddie W. Seay

AUG 27 1984

APPROVED BY Oil & Gas Inspector TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 23 1984

O.C.D.
HOBBS OFFICE