NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper

the Commission. Indicate nature of	of notice by checking below:		
NOTICE OF INTENTION TO TEST CASING SHUT-OFF	NOTICE OF INTENTION TO CHEMICALLY TREAT V	SHOOT OR WELL	
NOTICE OF INTENTION TO CHANGE PLANS	NOTICE OF INTENTION TO OTHERWISE ALTER CA	PULL OR SING	
NOTICE OF INTENTION TO REPAIR WELL	NOTICE OF INTENTION TO	PLUG WELL	x
NOTICE OF INTENTION TO DEEPEN WELL			
Art	esia, New Mexico	May 7th,	1945
OIL CONSERVATION COMMISSION, Santa Fe, New Mexico. Gentlemen:	Place	Date	
Following is a notice of intention to do certain work as J. C. Watson Drilling Co. Fowl. Company or Operator	ar-Woin		nk aru
Company or Operator Lease of Sec. 14, T. 24 S, R. 37E	N M D M Taxalia	M AA	- W.
Lea County.	, N. M. P. M.,	MADELX	_Field,
The above well was drilled to 36 the Fowler-Hair wells No. 1,2 & 3645. We propose to plug off and cement and test water shut	water in bottom of hol	arrying oil encountered e with lead	at wool
The above well was drilled to 36 the Fowler-Hair wells No. 1 2 &	3 was day. Water was water in bottom of holoff. Then fill hole we and put in 15 sacks pase of the 8 5/8" cas	arrying oil encountered e with lead ith mud to b of cement. ing set at]	wool ase We .290
The above well was drilled to 36 the Fowler-Hair wells No. 1,2 & 3645. We propose to plug off and cement and test water shut of salt, approximately 2500 feet will then fill with mud to the 18 and put in another 15 sacks of the 8 5/8" casing we will fill marker and clean up location.	3 was day. Water was water in bottom of holoff. Then fill hole we and put in 15 sacks pase of the 8 5/8" cas	arrying oil encountered e with lead ith mud to b of cement. ing set at]	wool ase We .290
The above well was drilled to 36 the Fowler-Hair wells No. 1,2 & 3645. We propose to plug off and cement and test water shut of salt, approximately 2500 feet will then fill with mud to the 18 and put in another 15 sacks of the 8 5/8" casing we will fill	3 was day. Water was water in bottom of holoff. Then fill hole wit, and put in 15 sacks case of the 8 5/8" cas of cement. After pull hole to surface with	arrying oil encountered with lead ith mud to he of cement. ing set at ling what we he mud, set possible co.	wool ase We .290