		TATEMATION TO:	1			
TEST WATER SHUT-OFF		Division of the second		SUBSEQU	ENT REPORT OF:	
FRACTURE TREAT		PULL OR ALTER CASING MULTIPLE COMPLETE	/	WATER SHUT-OFF	REPAIRING WELL	-
SHOOT OR ACIDIZE		ABANDON*		FRACTURE TREATMENT	ALTERING CASING	-
REPAIR WELL,		CHANGE PLANS		SHOOTING OR ACIDIZING	ABANDONMENT*	-
(Other)		2		(Other) Install pum	P & evaluate x	•
Proposed work. If we	MPLETE	D OPERATIONS (Clearly state	ali pertinent	Completion or Recomple	of multiple completion on Well tion Report and Log form.)	_

NM

17. DESCRIBE MONOMERETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any nent to this work.)*

Last record of work on well is clean-out & frac August 1955. Poor producer for last several years - oil & water kills gas flow. 2/10-19/77 Following work performed to evaluate:

- Pulled 2" tubing after tagging btm. at 3424' (TD 3525'). Found holes in top jt. of tubing.
- Cleaned out 12' of frac sand & cavings (open hole 3337-3525') to 3436' and pump quit loading. 500' fluid in hole.
- 3. Ran tbg. to 3420', BHP and 3/4" rods.
- Set Oilwell 57D unit w/C-66 gas engine.
- Started pumping 2-19-77. 2-25-77 averaging 152 MCF & 5 BWPD.

18. I hereby certify that the foregoing is true and correct BIGNED L. E. LOTT (This space for Federal or State office use)	TITLE Dist. Production Manager DATE 3-10-77		
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE	ACCEPTED FOR RECORD	
. *Sec	e Instructions on Reverse Side	MAR 14 1977	