

Fowler Ellenburger
South Mattix Unit No. 4
Repair

Purpose: To repair suspected casing leak

1. Rig up, load well and pull tubing.
2. Run work string with packer and bridge plug assemble to pressure test for casing leak. Isolate casing leak interval with packer and BP tests.
3. Run casing inspection log over leak interval to determine quality of remaining casing.
4. With leak located plugback with sand and squeeze below a drillable retainer.
5. Drill out and pressure test.
6. Repeat squeeze if necessary.
7. Return well to production.

RECEIVED

LA 51376

OIL CONSERVATION BOARD
ADAMS, W. W.