

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-75

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

1. CIL WELL ☒ GAS WELL ☐ OTHER ☐	7. Unit Agreement Name B-10709
2. Name of Operator SHELL WESTERN E&P INC.	8. Form of Lease Name STATE
3. Address of Operator P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)	9. Well No. 2
4. Location of Well UNIT LETTER <u>E</u> <u>1650</u> FEET FROM THE <u>NORTH</u> LINE AND <u>660</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>36</u> TOWNSHIP <u>24-S</u> RANGE <u>36-E</u> NMPM.	10. Field and Pool, or Whichever JALMAT
15. Elevation (Show whether DF, RT, GR, etc.) 3278' DF	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPER. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☒ OAP & ACID TREATED

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-26-85: Ran bit/scrapper to 2772'.

6-27-85: Perf'd Yates 2636' - 2656' (1 JSPF, 16 holes). Acidized Yates perf's 2636' - 2772' w/2000 gals 20% HCl-NEA. Set a RBP @ 2670'. Acidized Yates perf's 2636' - 2652' w/2000 gals 20% HCl-NEA. Pulled RBP. Installed production equipment and returned well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. Carter for A. J. FORE
ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

TITLE SUPERVISOR REG. & PERMITTING

DATE OCTOBER 25, 1985

OCT 29 1985

APPROVED BY _____

TITLE _____

DATE _____

RECEIVED

OCT 28 1985

O.C.D.
HOBBS OFFICE

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER		5a. Indicate Type of Lease State ☒ Fee ☐
2. Name of Operator SHELL WESTERN E&P INC.		5. State Oil & Gas Lease No. B-10709
3. Address of Operator P. O. BOX 991, HOUSTON, TEXAS 77001		7. Unit Agreement Name
4. Location of Well UNIT LETTER <u>E</u> <u>1650</u> FEET FROM THE <u>NORTH</u> LINE AND <u>660</u> FEET FROM THE <u>WEST</u> LINE, SECTION <u>36</u> TOWNSHIP <u>24-S</u> RANGE <u>36-E</u> N.M.P.M.		8. Farm or Lease Name STATE
		9. Well No. 2
		10. Field and Pool, or Wildcat JALMAT
15. Elevation (Show whether DF, RT, GR, etc.) 3278' DF		12. County LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANE ☐

OTHER OAP & ACID TREAT ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

1. Run bit/scraper to PBTD (2764') and clean out. Spot 100 gals 20% NEA from 2775' - 2625'.
2. Perforate Yates from 2636' to 2656' (1 JSPF, 16 holes).
3. Acid treat Yates perf's 2681' - 2772' w/2000 gals 20% HCl-NEA.
4. Set a RBP @ 2670'. Acid treat Yates perf's 2636' to 2656' w/2000 gals 20% HCl-NEA.
5. Install production equipment and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie Custer for A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE JUNE 13, 1985

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT 1 SUPERVISOR

JUN 17 1985

APPROVED BY _____ DATE _____

RECEIVED

JUN 17 1985

U.S. DEPT. OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION