

Form 3160-5
(June 1990)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Permitment

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

CONVEST ENERGY CORPORATION

3. Address and Telephone No.

2401 FOUNTAIN VIEW, SUITE 700, HOUSTON, TX 77057

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330' FNL & 1650' FEL, SEC. 35, T24S-R36E

5. Lease Designation and Serial No.

NML Co 32618A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

I.B. 066 A #6

9. API Well No.

30025225450007

10. Field and Pool, or Exploratory Area

JALMAT

11. County or Parish, State

Lea Co., NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒
- Notice of Intent
-
- ☐
- Subsequent Report
-
- ☐
- Final Abandonment Notice

TYPE OF ACTION

- ☒
- Abandonment
-
- ☐
- Recompletion
-
- ☐
- Plugging Back
-
- ☐
- Casing Repair
-
- ☐
- Altering Casing
-
- ☐
- Other
-
- ☐
- Change of Plans
-
- ☐
- New Construction
-
- ☐
- Non-Routine Fracturing
-
- ☐
- Water Shut-Off
-
- ☐
- Conversion to Injection
-
- ☐
- Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1.) Notify BLM prior to any work @ (505) 393-3612
- 2.) MI RU Rig. POOH w/ Production equip. LD all except +bg.
- 3.) Spot ~~2500'~~ ^{SUFFICIENT} Cmt. plug from 3140' to 2580'. tag plug.
- 4.) Displace hole w/ 9 ppg. mud (25 lbs GEL / BBL OF BRINE).
- 5.) Perf. 5 1/2" Csg. @ 422'
- 6.) Spot. 100' cmt plug ^{NOT LESS THAN 24 SACKS} from 422' - 322' ^(INSIDE AND OUTSIDE 5 1/2" CASING) Tag plug AT 322'.
- 6.A) DISPLACE HOLE w/ 9 ppg mud.
- 7.) Spot Cement plug FROM 50' TO SURFACE.
- 8.) Cut off Csgs. 4' below GL. weld on plate & DA marker.
- 9.) Level & restore location

14. I hereby certify that the foregoing is true and correct

Signed

E. L. Henderson

Title

Agent

Date

8/24/92

(This space for Federal or State office use)

Approved by

Adam Scimech

Title

Date

8/25/92

Conditions of approval, if any:

CEMENT SLURRY USED IN THIS OPERATION SHOULD BE CLASS 'C' CEMENT MIXED WITH FRESH WATER AT 14.8 PPG.

RECEIVED

AUG 28 1992

OCD HOBBS OFFICE