Form 9-331	•.
(May 1983) UNITED STATES SUBMIT IN TRIP ICATE DEPARTM T OF THE INTERIOR (Other instruct on re-	Form approved. Budget Bureau No. 42-R
GEOLOGICAL SURVEY	O. LEASE DESIGNATION AND SERIAL
	LC 032339 (
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEZ OR TRIBE N
OIL WELL GAS WELL OTHER 2. SAME OF OPERATOR	7. UNIT AGREEMENT NAME
3. LODRESS OF OPERATOR	8. FARM OR LEASE NAME
Box 460, Ho3BS, N.M. 88240 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* At surface	9. WELL NO.
	10. FIELD AND POOL, OR WILDCAT
2080' FSL & 2080' FEL OF SEC. 10	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)	SEC. 10 T-245 R-37 12. COUNTY OR PARISH 13. STATE
6. Check Appropriate Box To Indicate Nature of Notice, Report, or Of	LEA N.M.
SUBSECUE	her Data
PULL OR ALTER CASING	
MULTIPLE COMPLETE	REPAIRING WELL
SHOOT OR ACIDIZE ABANDON* SHOOTING OF ACIDIZE	ALTERING CASING
REPAIR WELL CHANGE PLANS SHOOTING OR ACIDIZING	ABANDONMENT*
(Other) (Other) (Note: Report results of	multiple
7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details and deta	multiple completion on Well ion Report and Log form.)
7. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, in nent to this work.) *	cluding estimated date of starting a
	at a contract of the con
It is proposed to set ptr@ 17350' & sp	pot 1000 gals
acid 7350'-7470' & let sook for 30 min.	Trest with
additional 1000 gals 28% acid. Shut in	for 2 hrs
before returning well to prod. status.	
70 100. 372723.	
I hereby certify that the rolegoing is true and correct	
TITLE SR. ANALYST This space for Federal or State office use)	DATE 9-13-74
APPROVED BY	BANK DESIGNA
William I am a man a	T N J

USGS-5, NMFU-4, File

*See Instructions on Reverse Side
JIM SIMS
ACTING DISTRICT ENGINEER