

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State ☒ Fee ☐
5. State Oil & Gas Lease No. B-2659
7. Unit Agreement Name
8. Farm or Lease Name State A-16
9. Well No. 1
10. Field and Pool, or Wildcat Langlie Mattix Trvs Queen
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. Name of Operator CONOCO INC.
3. Address of Operator P. O. Box 460, Hobbs, N.M. 88240
4. Location of Well UNIT LETTER <u>M</u> <u>330</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>16</u> TOWNSHIP <u>24S</u> RANGE <u>37E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER <u>blast frac</u> ☒	CASING TEST AND CEMENT JOBS ☐	OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU. CO to 3568'. Set RBP @ 3329'. Run CBL & variable density log & locate TOC while going in hole. Log from 3324'-3000' & pull up hole & log from 200' below the TOC to 200' above the top. If wellbore is clean to PBTD, dump 39 gals of limestone pea gravel down open ended tbg. If wellbore is not clean to PBTD but below 3568', dump a volume of limestone pea gravel calc. as follows: (Top of fill - 3558') x 1.0249 = * gals gravel. Place 230 gals of Tovex 836 explosives across interval from 3558'-3334'. Load wellbore to surface w/82 bbls TFW. Set detonating bombs above explosives @ 3334'. Place 10 gals limestone pea gravel on top of bombs. Place 103 gals Cal-seal on top of gravel. Leave well open & piped to pit. DO cal-seal to the pea gravel @ 3324' w/stable foam. Run prod. equipment & place well on test.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ann Bull TITLE Administrative Supervisor DATE 5/23/85

APPROVED BY ORIGINAL SIGNED BY JERRY DEXTON DISTRICT SUPERVISOR TITLE _____ DATE MAY 28 1985
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

MAY 24 1985

U.S. DEPT. OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION