

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

| | |
|--|--|
| WELL API NO. | 30-025-25236 |
| 5. Indicate Type of Lease | STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> |
| 6. State Oil & Gas Lease No. | |
| 7. Lease Name or Unit Agreement Name | WOOLWORTH, C. D. |
| 8. Well No. | 019 |
| 9. Pool name or Wildcat | JALMAT-YATES-7R SWD |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) | 3328' RKB |

| | |
|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER SWD | |
| 2. Name of Operator Phillips Petroleum Company | |
| 3. Address of Operator 4001 Penbrook Street, Odessa, TX 79762 | |
| 4. Well Location Unit Letter F : 1650 Feet From The NORTH Line and 2310 Feet From The WEST Line Section 26 Township 24-S Range 36-E NMPM LEA County | |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3328' RKB | |

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: PLUG AND ABANDON WELL. ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

07/10/96 MIRU SIERRA WS #3 & CMT EQMT, ND WELLHEAD & NU CL I BOP, USE WELDER T/HEAT TBG DO-NUT & PACKOFF, LD 100 JTS 2.875" INJ TBG & AD-1 PKR, SDON.
07/11/96 PU 100 JTS 2.375" WS & GIH W/CIBP, MIX 50 SX SALT GEL W/100 BBLS 10# BRINE, ATTEMPT T/SET ALPHA CIBP, TRACH & SCALE PLUGGING BTM PORT OF CIBP, TOH LD CIBP & GIH W/NEW ALPHA CIBP SET @ 3151', CIRC W/30 BBLS 10# MLF, PMP PLUG #1, 60 SX 3151' - 2559', CL C 14.8 PPG 1.32 CFPS, TOH W/WS, ND BOP & WH, SCREW 5.5" PULL JT ON BELL NIPPLE, REMOVE PACKOFF & SLIPS, NU BOP, FREEPOINT INDICATES FREE @ 2200'+/-, SDON.
07/12/96 RU WL TRUCK & CUT 5.5" CSG @ 1400', RD WL TRUCK, RU CASING TOOLS, LD 36 JTS 5.5" CSG, RD CASING PULLERS RU TUBING TOOLS, TIH T/1452', LD W/40 BBL 10# MLF, PMP PLUG #3, 75 SX 1450'-1166', TOH W/WS, SDON.

(CONTINUED ON BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Larry M. Sanders* TITLE Senior Regulation Analyst DATE _____
TYPE OR PRINT NAME Larry M. Sanders TELEPHONE NO. (915)368-1488

(This space for State Use)

APPROVED BY *Charles Perry* TITLE _____ DATE JAN 28 1997
CONDITIONS OF APPROVAL, IF ANY:

C.D. WOOLWORTH #D19 (CONTINUED)

07/15/96 TIH & TAG PLUG #3 @ 1392', OK'D BY NMOC D TO SPOT 40 SX BAL PLUG MIXED W/2%
CACL 1392'-1253', WOC & TAG, RU WL TRUCK & GIH TAG PLUG #4 @ 1370', RD WL
TRUCK, SPOT PLUG #5 75 SX MIX W/2% CACL 1370'-1126', WOC & TAG, RU WL TRUCK
& TAG PLUG #5 @ 1126', RD WL TRUCK, TIH T/308', PMP PLUG #6 80 SX 308'-3', CMT
CIRC T/SURF LEAVING INSIDE OF 8.625" CSG FULL, LD WS & WASH UP TOOLS W/FW,
ND BOP, DIG OUT CELLAR, CUT & CAP INSTALL DRY HOLE MARKER, PERFORM
RECLAMATION, RDMO, WELL PA'D.

COMPLETE DROP FROM REPORT