

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
Amoco Production Company

3. ADDRESS OF OPERATOR
P.O. Drawer A, Levelland, Texas 79336

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
990' FSL & 1980' FEL (Unit 0, SW/4, SE/4) Section 4

RECEIVED

JUN 8 1978

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

5. LEASE DESIGNATION AND SERIAL NO.
NM-7488

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Myers B Federal

9. WELL NO.
27

10. FIELD AND POOL, OR WILDCAT
Jalmat Yates Seven Rivers

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA
4-24-37

12. COUNTY OR PARISH
Lea

13. STATE
NM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3295.87 RDB

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
(Other) <input type="checkbox"/>	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Propose to plug and abandon this well using the following procedure:

1. Set bridge plug at 2600'. Cap with 100' of cement
2. Fill hole with mud laden fluid.
3. Spot 100' cement plug 1050'-1150'.
4. Spot 10 sacks surface plug and erect abandonment marker.

I hereby certify that the foregoing is true and correct.

SIGNED A. V. Lenczy TITLE Admin. Analyst

DATE 6-6-78

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

1+4-USGS-H
1-Div
1-Susp
1-AVH

*See Instructions on Reverse Side

APPROVED
AS AMENDED
JUN 8 1978
ACTING DISTRICT ENGINEER